SITE DISCOVERY REPORT

North Orange County Site Discovery Project DTSC – Cypress Region

Cooperative Agreement No. V-97999001-2

February 2011

Prepared for: U.S. Environmental Protection Agency Region 9

Prepared by: Rafiq Ahmed
Cal/EPA Department of Toxic Substances Control
5796 Corporate Ave. Cypress, CA 90630

Signatures and Concurrence:

	War.	Lolina	
DTSC Unit Chief:	/ sun	A Provide	

Greg Holmes
Type Name Signature

EPA

Concurrence:

Table of Contents

Secti	on Page
1.0	INTRODUCTION
2.0	PROJECT DESCRIPTION
3.0	HYDROGEOLOGIC SETTING7
4.0	OPERATIONAL HISTORY OF THE PROJECT AREA
5.0	REGULATORY AGENCIES INVOLVEMENT
6.0	SOURCES OF INFORMATION126.1Site Identification Criteria126.2Site identification Sources136.3Sanborn Maps Data136.4Investigative Efforts13
70	PRIORITIZATION METHODOLOGY14
8.0	HAZARD RANKING SYSTEM FACTORS14
9.0	SUMMARY15
10.0	DELIVERABLE15
11.0	LIST OF DOCUMENTS INCLUDED16

List of Acronyms

EPA Environmental Protection Agency

DTSC Department of Toxic Substances Control RWQCB Regional Water Quality Control Board

CERCLA Comprehensive Environmental Response, Compensation, and Liability Act

SARA Superfund Amendments and Reauthorization Act

CERCLIS Comprehensive Environmental Response, Compensation, and Liability

Information System

CUPA Certified Unified Program Agency
MCLs Maximum Contaminant Levels

μg/l microgram per liter

1.0 INTRODUCTION

Under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA), the California Environmental Protection Agency, Department of Toxic Substances Control (DTSC), Cypress Region was tasked to conduct a U.S. Environmental Protection Agency (EPA) Site Discovery Project for sites in the North Orange County (North OC), California area. The purpose of this North OC Site Discovery Project (Project) is to identify potential sources of groundwater contamination which has caused the closure of four production wells and threatened several other production wells. A Workplan for this Project was approved by EPA on December 6, 2010 (Attachment 1)

More information about the Superfund program is available on the EPA web site at http://www.epa.gov/superfund.

1.1 Apparent Problem

Orange County Water District (OCWD) is responsible for managing the vast Orange County Ground Water Basin (basin) under north and central Orange County (OC) that supplies water to more than 20 cities including the City of Fullerton and other water agencies, serving more than two million OC residents. Various investigations conducted by OCWD and others have revealed that groundwater in the northern portion of the basin is contaminated with volatile organic compounds, or VOCs. From the late 1950s through early 1980s, VOCs were used for industrial degreasing in metals and electronics manufacturing. VOCs were released into the environment and impacted the shallow aquifer, which is generally less than 200 feet deep. A very large multi-source groundwater contamination plume (Figure 1) is suspected to have been caused by past and present chemical handling practices of the sites in this area. Groundwater contamination originating in the shallow aquifer continues to migrate both laterally and vertically in response to hydraulic gradients in the area. Based on water level measurements collected from OCWD monitoring wells in 2005, depth to groundwater in the upper shallow aquifer system ranges from approximately 80 to 120 feet below ground surface (bgs).

To protect public health, the City of Fullerton shut down production wells F-FS13 and F-KIM1 in 1999 and 2001, respectively, as a result of increasing tetrachloroethene (PCE) concentrations. These wells were subsequently destroyed in 2002. The basin contains several production wells that are threatened by the contamination plume. In particular, well FM-8 has been found to contain high levels of tetrachloroethene (PCE), trichloroethene (TCE) and 1, 1-dichloroethene (1,1-DCE) contamination. FM-8 well is one of the monitoring wells in the Fullerton area. Other VOC chemicals such as 1,2-dichloroethane (1,2-DCA) and 1,2,3-trichloroethane (1,2,3-TCP), 1,4-dioxane, perchlorate, and nitrate, have been also found in groundwater beneath the project area. TCE and PCE have been detected at levels exceeding 5 and/or 10 times the MCLs at sites in the project area. These sites pose a serious threat

specifically to the groundwater wells in the area and to human health and the environment in general.

1.2 Proposed Solution

OCWD has investigated groundwater conditions in the North Basin Area, and has prepared and updated a focused feasibility study to address groundwater contamination in the North Basin Area. OCWD has also filed lawsuits naming companies suspected to be the sources of the VOC and/or perchlorate contamination. DTSC's task was to review database information and site files, and conduct file search and field surveys, to discover additional potential contamination source sites. The additional identified sites were added to a project database together with other relevant information.

DTSC reviewed the comprehensive lists of sites from its own programs and other regulatory agencies. These include DTSC's databases HAZNET (HWTS), STARS, Tiered Permitting and EnviroStor, RWQCB's GeoTracker, and Orange County Health Care Agency (OCHCA)'s CUPA sites list. These databases were either accessed online or from their file room record to compile project database of all the sites in the Project area. The sites within less than one-mile from FM-8 well were entered in a Microsoft Excel spreadsheet with other relevant information to constitute the Project Data Sheet/Database (**Table 1**).

A Geographic Information Systems (GIS) tool available in DTSC's Intranet and an on-line tool at www.johndcook.com/lat_long_distance.html was used to determine the latitude and longitude of a site and whether the site was within one-mile of FM-8 well's location. The sites within a one-mile radius from FM-8 well were selected because such sites have a higher likelihood of being potential contributors to groundwater contamination in the FM-8 well.

Using eight (8) scoring criteria, sites were prioritized and sorted from the highest scoring sites to the lowest scoring sites using the Project Priority Chart (**Table 2**).

2.0 PROJECT DESCRIPTION

The North Orange County (OC) Site Discovery Project was conducted in the southeast portion of the city of Fullerton in Orange County, California. The study area of the North OC Site Discovery Project (Project Area – **Figure 2**) is bounded by South State College Boulevard to the east, E. Commonwealth Avenue and S. Lillie Avenue to the north-east, S. Raymond Avenue to the west, E Walnut Avenue to the north, and E. Kimberly Avenue to the south. This area was chosen because it may contain the sources of groundwater contamination contributing to a regional plume impacting the FM-8 well, The maximum concentrations of trichloroethene (TCE), tetrachloroethene (PCE), 1,1-Dichloroethene (1,1-DCE) and 1,4-Dioxane detected in FM-8 well were 91.6 µg/l, 64.5 µg/l, 55.8 µg/l and 2 µg/l respectively, for the period of May 2001 through April 2010 (**Table 3**). Groundwater in the Project Area generally flows from east to the west, in the direction of FM-8 well. Currently the source of contamination of FM-8 well is unknown.

DTSC's project builds on the efforts of the Orange County Water District (OCWD) to identify sources of groundwater contamination. The study area for OCWD's North Basin Groundwater Protection Project (NBGPP) includes the area of DTSC's North OC Site Discovery Project. The purpose of this project is to identify potential sources of groundwater contamination which have caused the closure of four production wells and threatened several other production wells. **Table 4** shows contaminant concentrations in extraction wells in the Fullerton area.

2.1 Project Study Area Location

The project study area includes a major portion of southern part of the city of Fullerton, Orange County, California. The project study area is located on the north side of the State Route (SR)-91 Freeway. The Project Area was selected to be within one-mile of FM-8 well which is located near the intersection of East Walnut Avenue and South Raymond Avenue in Fullerton.

3.0 HYDROGEOLOGIC SETTING

The Project Study area is located within the Orange County Groundwater Basin (basin) which is part of the 360-sqaure-mile Coastal Plain of Orange County. The Santa Ana River, the primary surface water drainage feature in the area, is located east and southeast of the Project Area. OCWD manages groundwater recharge and pumping to ensure that the basin is not overdrawn. OCWD recharges the basin with water from Santa Ana River (SAR) and to a lesser extent with imported water purchased from the Metropolitan Water District of Southern California. The northern portion of the basin, which includes the cities of Fullerton and Anaheim, falls within the region known as the Forebay, which is predominant area of the basin recharge. The basin contains two aquifers that are separated by a fine-grained layer at a depth of approximately 200 to 250 feet. OCWD has divided the aguifers into three aguifer systems defined by regional aquitards, differences in potentiometric surfaces, and changes in water quality. The Shallow Aquifer System includes sediments extending to an average depth of approximately 150 feet beneath the Study Area. The Principal Aquifer System contains unconsolidated strata extending to an average depth of about 850 feet. The Deep Aquifer System contains the unconsolidated aquifers below about 900 feet, extending to an average depth of 1,300 feet beneath the Study Area. Groundwater in these systems generally occurs under unconfined conditions in the northern Study Area and under semi-confined to confined conditions in the south. In the northern section of OCWD's groundwater basin (under Fullerton and Anaheim), portions of the shallow aquifer are contaminated with VOCs. Groundwater contamination in the NBGPP is primarily found in the shallow aguifer, which is generally less than 200 feet and is not directly used for drinking water supply.

The depth to groundwater in the shallow aquifer system ranges from approximately 80 to 120 feet bgs. The groundwater flow is from east to west beneath the project Study Area but its flow may change seasonally and over time due to changes in the pumping patterns and the rainy seasons. The highest groundwater contamination in the Study Area has been found in the Shallow Aquifer System.

4.0 OPERATIONAL HISTORY OF THE PROJECT AREA

The Project Area was previously used for agricultural purposes from 1920 to 1954. Since then, numerous industrial facilities (sites) have contributed to groundwater contamination in the area. The California Regional Water Quality Control Board (RWQCB), Santa Ana Region, identified several sites potentially responsible for groundwater contamination in the north basin. The sites suspected to be major contributors to the groundwater contamination plumes in the Project Area include American Electronics aka Graphics 2000, Johnson Controls aka Southern California Edison, Programmed Composites, Chicago Musical Instruments aka United Duralume, EDO Corporation aka USF/Reddaway, S C I F Fullerton (former Weber Aircraft) aka Weyerhaeser Company, Orange County Metal Processing, Alco Fastening Systems, Mesa Cold Storage, PCA Metals, and Allergan aka Inland Computer Products, and may include many other sites. All of these sites may be associated with groundwater contamination plumes that are suspected to have been caused by past and present chemical handling practices.

4.1 Operational History of Major Sites in the Project Area

The operational history of some of the major sites in the Project Area is listed below:

FORMER WEBER AIRCRAFT FACILITY: Prior to Weber's occupancy of the property, CBS, Inc. aka Fender Musical Instruments (Fender) occupied the property. Fender's operations at the site included the use of chemical dipping tanks and underground storage tanks. Some of the manufacturing processes utilized at this site required the use of spray painting, chemical plating, degreasing and chemical storage.

In July and August of 2001, Arcadis performed a subsurface soil investigation that included the collection of soil vapor samples from soil vapor probes and the collection of soil samples from soil borings. With the exception of Area 4, where a generator that used natural gas was located, four of five designated areas at the site were investigated. These areas included:

Area 1 - Southwest Building Process Room, PCE Degreaser, and West Dock;

Area 2 - Southwest Former Dip Tank Shed;

Area 3 - Chemical Storage;

Area 4 - Southside Vent Pipe; and

Area 5 - Southeast Former Underground Storage Tanks.

Soil vapor samples SV-1 through SV-6 were collected from Area 1, and soil vapor samples SV-7 and SV-8 were collected from Area 3. The highest concentrations found were 1,1 -DCE and PCE, which were detected in SV-5 at 20 feet bgs.

Arcadis collected soil samples from eight soil borings, SB-1 thru SB-8. Concentrations of PCE ranging from 15 μ g/kg to 21. 0 μ g/kg were reported in the soil samples collected from SB-3 and SB-4.

From November 11, 2001 to January 18, 2002, Arcadis performed the additional soil and initial groundwater sampling activities at the site. Four groundwater monitoring wells (MW-1 through MW-4) were installed to establish the groundwater flow direction beneath the site, and to assess the VOC impact to the groundwater near the existing solvent degreaser along the west side of the facility. TCE was found in concentrations ranging from 45 μ g/l to 150 μ g/l, with the highest concentration found in MW-1 PCE was found in concentrations ranging from 2.8 μ g/l to 19 μ g/l, with the highest concentration found in MW-2.

In June 2002, MW-5 was installed adjacent to MW-1 and in the vicinity of the PCE degreaser. Analytical results of soil samples collected from the MW-5 boring indicated the presence of PCE, ranging in concentrations from 7.2 μ g/kg to 63 μ g/kg, with the highest concentrations found at 10 feet bgs, and TCE, ranging in concentrations from 17 μ g/kg to 47 μ g/kg, with the highest concentrations found at 70 feet bgs. The analytical results for groundwater samples collected at approximately 120, 135, and 151 feet bgs indicated the presence of PCE and TCE in concentrations ranging from 7.6 μ g/l to 23 μ g/l

Alcoa Fastening Systems, Inc.: The facility is a manufacturer of fasteners for the aerospace industries. The manufacturing of fasteners at the site began under Microdot, Inc. in 1962. Microdot, Inc. filed for bankruptcy and the business was bought by Kaynar Manufacturing in 1993. Fairchild Fasteners purchased the facility and later sold it to Alcoa Fastening Systems in December 2004. The fastener manufacturing process involves forming, machining, heat treating, and electroplating of aluminum, titanium, steel alloys and stainless steels. The electroplating process involves the use of cadmium, silver, nickel, copper, chromium and zinc plating solutions. In 1996, the facility conducted soil and soil gas investigations and found a maximum concentration of 14,130 μ g/kg tetrachloroethylene (PCE) in soil, and 2,541 μ g/l in soil gas.

Johnson Controls (Battery Group), Inc.: The property was developed from agricultural land in 1956 and battery manufacturing began in the mid 1960s by Globe Union. In 1978 Globe-Union merged with Johnson Controls Battery Group, Inc. The facility was granted RCRA Interim Status on March 30, 1981. The facility received Acceptance of Closure Certification on June 12, 1995. A Phase I Environmental Assessment Checklist declaring "further investigation not necessary" was submitted on 2/27/97. Groundwater Contamination: Groundwater was investigated at the facility by collecting groundwater samples from two onsite groundwater monitoring wells. Sample results show PCE at concentrations ranging from 3.7 to 10 micrograms per liter (μg/l) and TCE concentration ranging from 13 to 33 μg/l. JCI is located within a regional VOC groundwater plume and site-specific groundwater cleanup is not a viable option considering the low concentration beneath the site and continued migration of contaminated groundwater from up gradient sources. The VOC concentrations in groundwater at the site are at or below the concentrations observed in the regional VOC plume.

PCA Metal Finishing: The site is an inactive electro-chemical facility located in an industrial and manufacturing area. The site occupies approximately 97,000 sq. feet. The facility consists of two contiguous properties with separate addresses. In a letter dated April 20, 1990, the Santa Ana Regional Water Quality Control Board requested the facility to submit a report about its use of organic solvents and submit a workplan for conducting a subsurface investigation to identify any presence of solvents in the soil. As a result of the investigation, a release of chlorinated solvents in nearby public water wells was discovered. A regional investigation of groundwater impact in the area has documented that there were multiple sources for the chlorinated solvents in the groundwater. On August 12, 1993, the facility obtained Conditional Authorization under DTSC's Tiered Permitting program and on September 12, 1995 it was upgraded to a Permit-By-Rule (PBR) authorization to treat hazardous wastewater and to manage sludge. Subsequently, 157 soil samples were collected from 54 different borings and groundwater samples were collected on several occasions from six groundwater monitoring wells located within 200 feet of the center of the site. The investigations confirmed releases of chlorinated solvents at the site. In 2006, the facility began closing its operations under the oversight of Orange County Health Care Agency and ceased manufacturing operations entirely by mid March 2007. The County has referred the site to DTSC's Enforcement Branch for further action.

Orange County Metal Processing (OCMP): The site is a metal finishing shop which coats metal parts with finishes for metal, used by automobile and computer manufacturers. The area of the property is approximately 14,000 square feet. OCMP was authorized to operate a Tiered Permitting On-Site Hazardous Waste Treatment System (System) under the Conditional Authorization Tier (DTSC 1772) on April 1, 1993. OCMP submitted a Phase I Environmental Assessment Checklist as required by Health & Safety Code Section 25200.14 on December 23, 1996. The contaminants detected during sample analysis were cadmium, chromium, copper, zinc and VOCs. Predominant VOCs were PCE and TCE. Review of the results showed contamination throughout the site in soil and groundwater.

Chicago Musical Instrument (CMI): The site was previously used for agricultural purposes until 1954 when a musical instrument manufacturer F E Olds and Son, Inc. (Olds), constructed a new industrial building at the site and moved its manufacturing facility from Los Angeles to the site. Sometimes during this period, CMI merged with Olds and eventually took over the ownership of Olds. According to OCWD records, CMI was purchased by Norlin Industries, Inc. which is now defunct. CMI manufactured musical instruments and brass parts at the site. CMI reported conducting nickel, silver, and gold plating at the site and constructed several sumps within the manufacturing building. In 2009, OCWD conducted a soil gas survey at the site and detected TCE at concentrations ranging between 520 and 1,300 μ g/l, PCE at concentrations ranging between 1,300 and 4,7000 μ g/l as well as 1,1-DCE at concentrations between 1,200 and 1,700 μ g/l. A sampling and analysis plan (SAP) is being initiated to evaluate the potential presence of chemical constituents in soil gas, soil, and groundwater at the site.

American Electronics, Inc. On June 20, 1996, a no further action letter was issued for the groundwater at this site. This letter was conditioned upon maintenance of existing monitoring wells BP-2, BP-3, BP-4 and BP8, and annual monitoring of these wells for at least two years.

Annual monitoring of wells BP-2, BP-3, BP-4 and BP-8 was conducted in November 1996 and December 1997. The December 1997 report indicates that trichloroethene (TCE), tetrachloroethene (PCE), and 1,l-dichloroethene (DCE) were detected at maximum concentrations of 22.90 and 3.1 micrograms per liter (μ g/l), respectively. Toluene was reported at concentrations ranging from 19 to 29 μ g/l and 1,2-dichloroethane (DCA) was detected at concentrations ranging from 2.5 to 5.2 μ g/l. Toluene appears to have been introduced as a lab contaminant and 1,2-DCA has been detected only sporadically in these wells in the past.

5.0 REGULATORY AGENCIES INVOLVEMENT

Agency files were not reviewed as part of this project, because that work is part of the site screening task in the current PA/SI Cooperative Agreement. Individual site screening or site reassessment will be conducted on selected sites to determine the site-specific details.

5.1 U.S. Environmental Protection Agency (EPA)

EPA's CERCLIS database was reviewed. Sites in CERCLIS are flagged in the project database as active, archived or none, and will be designated for potential site reassessment instead of site screening.

There is no information indicating that any of the currently unregulated sites, (i.e. sites not known to be under current oversight by any agency) had previous involvement with EPA.

5.2 Department of Toxic Substances Control (DTSC)

Sites were checked against DTSC's EnviroStor database. For sites in EnviroStor, the information was used to populate the EnviroStor Status field in the project database. DTSC's HAZNET database was reviewed for manifest information on types and volumes of waste streams and any cleanup waste shipped off site. EnviroStor shows no current or significant past DTSC involvement with any of the currently unregulated sites. This Site Discovery Project has been incorporated into the work of the Cypress Cleanup Program under the Orange County Groundwater (OCGW) Team.

5.3 Regional Water Quality Control Boards (RWQCBs)

The Regional Water Quality Control Board's (RWQCB) "GeoTracker" database was reviewed. For sites in GeoTracker, the information was used to populate the RWQCB field of the project database as "Open-Remediation" or "Completed/Closed) with date, where available.

5.4 County and City Certified Unified Planning Agencies (CUPAs)

A list of sites in the project area and contamination information from the Orange County Health Care Agency (OCHCA) was received. This information was found at:

http://ochealthinfo.com/regulatory/downloads/reports.htm

The currently unregulated sites were not included on OCHCA's list.

5.5 Orange County Water District (OCWD)

The OCWD was established by the state legislature in 1933 to protect the water resources of Orange County and to represent the County's water purveyors. OCWD monitors groundwater wells, collects water quality data, and coordinates the use of groundwater in the County. OCWD initiated the South Basin Groundwater Protection Project in an effort to address groundwater contamination in the southeast Santa Ana and surrounding area. DTSC has attended several meetings with OCWD in which this Site Discovery Project was discussed, among other topics. OCWD provided DTSC with a Composite VOC Plume Map and data for contamination concentrations detected in FM-8 and other wells in the Project Area.

6.0 SOURCES OF INFORMATION

The following sources of information and methodology were used to collect and input information in the project database as proposed by DTSC.

6.1 Site Identification Criteria

First, business listings showing activities involving aerospace, plating, metal fabrication and finishing, machining, plastics, dry cleaning, printed circuit boards, electronic design and manufacturing, chemical manufacturing and distribution, machine tool and die shops, and adhesive manufacturing were used to select the potential sites to be reviewed for the site discovery project.

Second, HWTS sites with total yearly tonnage of one ton or more, with the following waste codes, were included in the Project database:

<u>Code</u>	Category Waste
211	Halogenated Solvents
351	Organic Solids with Halogens
611	Contaminated Soils from site cleanup
352	Other Organic Solids
214	Unspecified Solvent Mixture
343	Unspecified Organic Liquid Mixture
741	Liquids w / Halogenated Organic Comp & qt; = 1000 MG/L
342	Organic Liquids with Metals
251	Still Bottoms with Halogenated Organics
	Blank/Unknown (this category was selected due to the large number of manifests with this designation)

6.2 Site Identification Sources

- 1 U.S. EPA's CERCLIS database was checked for site status (active, archived, or not in CERCLIS). The Project database indicates which sites are in CERCLIS, so DTSC can separate the list into sites for future screening and reassessment.
- DTSC's Hazardous Waste Tracking System (HWTS) was reviewed to identify generators of hazardous waste containing VOCs
- 3 DTSC's EnviroStor database, the RWQCB's Geotracker database, and the Orange County Health Care Agency (OCHCA) sites list were checked to identify sites listed in those programs
- 4 Compiled evidence was reviewed to identify sites with confirmed contamination, for future site screening, and for enforcement if necessary
- 5. A drive-by survey was conducted to confirm site addresses and size.

6.3 Sanborn Maps Data

DTSC contacted the History Room of Fullerton Public Library about the availability of Sanborn Insurance Maps data and/or Polk's Guide for reference for the period of 1940 to1970 for the city of Fullerton. Unfortunately, there were no Sanborn Maps for the requested area. Polk's Guide for the area was also not available.

6.4 Investigative Efforts

The above-referenced databases and lists were reviewed and investigated to select a total of 171 sites which were found to be within the Project Area. All of the relevant site information was entered into the Project database. Forty one (41) sites were found to be listed in OCHCA/CUPA's website. Only two (2) sites were listed in the CERCLIS database, twelve (12) sites were listed in GeoTracker and eight (8) sites were in EnviroStor. However, 126 sites were not listed in any of these databases and therefore are regarded as "unregulated" sites

7.0 PRIORITIZATION METHODOLOGY

The total score for each site out of maximum of 20 points were added to determine the priority of the site according to the following eight criteria:

No	Criteria	Points Assigned	Total
1	Site Distance from FM-8 well	0 - 0.25 mile = + 3 0.25 - 0.50 mile = + 2 0.50 - 0.75 mile = + 1 0.75 - 1.00 mile = + 0	3
2	Is the site known to have used solvent (>1 ton total) on a regular basis?	Yes = +3 No = 0	3
3	Does the site lie within the footprint of a localized plume?	Yes = +2 No = 0	2
4	Is the site currently under a regulatory order for investigative or remedial action?	Yes = 0 No = +3	3
5	Number of years site has been in operation at this location	21+ yrs > = +3 11 - 20 yrs = +2 0 - 10 yrs = +1	3
6	Use of halogenated organic compounds listed in DTSC's HWTS Database	Yes = +2 No = 0	2
7	Size of the site/property	Large : > 1 acre = + 2 Medium:0.25 - 1.0 acre = + 1 Small : < 0.25 acre = + 0	2
8	Have the site disposed large volumes of manifested waste (> 1 ton total) as Blank/unknown?	Yes = +2 No = 0	2
		Maximum score	20

The Project Priority Chart was sorted from higher scoring sites to lower scoring sites. The sites at the top of the Project Priority Chart scoring 15 or more points, with no active regulatory involvement, provided a short list of sites for future Site Screening or Site Reassessment (**Table 5**). The sites found in the CERCLIS database are highlighted in the Project Priority Chart.

8.0 HAZARD RANKING SYSTEM FACTORS

The National Contingency Plan [40 CFR 300.415 (b) (2)] authorizes EPA to consider emergency response actions at sites that pose an imminent threat to human health or the environment. With the current level of information on all of the evaluated sites, a referral to EPA's Emergency Response Section is not warranted at this time. However, specific information will be determined when site screenings or re-assessments are conducted for these sites.

9.0 SUMMARY

It was determined that 126 sites in the project area are not being actively overseen by EPA, DTSC, RWQCB, or OCHCA. Some of these sites may pose a threat to human health and/or the environment. Of the 171 total potential sites in the project area, 3 sites are already under investigation, and 21 sites (scoring 15 or above out of 20 maximum) are recommended for site screening. The two sites recommended for reassessment rather than screening, Ruan Transportation Corporation and PCA Metals, have been chosen because these site are listed in CERCLIS. Sites already listed in CERCLIS do not require screening.

10.0 DELIVERABLE

DTSC has produced and finalized this Site Discovery Report according to the approved template for the North OC Site Discovery Project. Some of the highest priority sites will be included in this fiscal year's Workplan for the DTSC - EPA Cooperative Agreement, the remainder to be screened during next fiscal year, subject to U.S. EPA's approval.

11.0 LIST OF DOCUMENTS INCLUDED

TABLES

Table 1 -	Project Data Sheet/Database (Source: DTSC)
Table 2 -	Project Priority Chart (Source: DTSC)
Table 3 -	Key Parameter Concentrations in Well No.FM-8 (Source: OCWD)
Table 4 -	Key Parameter Concentrations in Monitoring Wells (Source: OCWD)
Table 5 -	List of Sites Recommended for Site Screening or Site Re-assessment (Source:DTSc)

FIGURES

Figure 1 - Project Area Map (Source: DTSC EnviroStor)
Figure 2 - Composite VOC Plume Map (Source: OCWD)

ATTACHMENTS

Attachment 1 - North Orange County Site Discovery Workplan (Source DTSC, Approved by EPA)

TABLES

Table 1

Project Data Sheet/Database (Source:DTSC)

				Т	1			Detections of	1		1	1]	Ī	1	T				1
3400					Distance			Chemicals of										HAZNET Waste			İ
Mag Ref	²				(feet) - Direction	Property Acres		Concern (PCE, TCE, perchlorate in			Overseeing Regulatory		CERCLIS	Envirostor	GeoTracker	County HCA		Types and Quantities (in		Drive-by Date and	Site Screening or
No.	Site Name	Address	City	Zip	From FM	1 ' '	Regulatory List	Groundwater)	Latitude	Longitude	Agency	Date	Status	Status	Status	Status	EPA ID#	tons)	HWTS California Waste Codes & Descriptions	Info	Reassessment Priority
	Acacia Career Training Facility (aka North Orange		1								1					Nothing					
1_	County Regional Occupational Center)	301 S. Acacia Ave.	Fullerton	92831	1 1742 - E	0.23 acres	DTSC- HWTS	Unknown	33.86839	-117.89827	None	9/13/2010	None	None	Nothing found	_	CAL000120418	Nothing Found	Nothing Found	11/30/2010	8
2	Siegling America	350 S. Acacia Ave.	Fuilerton	92831	1 1769 - E	> 0.25 acres	DTSC- HWTS	Unknown	33.86761	-117.89818	None	9/13/2010	None	None	Nothing found	Nothing	CA1000120402	Nothing Found	Nishing Farred	14 (20 /2040	
	a seguing i with the	355 61 7 656.4 7 11 6.					Disc iiivis	OII.KIIG#II	33.00701	-117.05010	Hone	3/13/2010	None	Itone	reothing round	Nothing	CALGOOT33432	INOLINE FOUND	Nothing Found	11/30/2010	9
3	FAAC International, Inc.	357 S. Acacia Ave.	Fullerton.	92831	1 1749 - E	0.11 acres	DTSC- HWTS	Unknown	33.86749	-117.89826	None	9/13/2010	None	None	Nothing found	Found Nothing	CAL000350728	Nothing Found	Nothing Found	11/30/2010	8
4	SAAC International, Inc.	357 S. Acacia Ave. Unit 357	Fullerton	92831	L 1749 - E	0.11 acres	DTSC - HWTS	Unknown	33.86749	-117.89826	None	9/13/2010	None	None	Nothing found	_	CAC002649655	Nothing Found	Nothing Found	11/30/2010	8
										ļ						Closed as of	CAC001330424	0.17	343 - Unspecified Organic Liquid Mixture 741 - Liquid with Halogenated Organic Compound		
	Omni Optical (aka Omni Optical Products Inc.;						OCHCA LUST.								Completed -	5/27/1988;	CAP000040006		211 - Halogenated Solvents	1	
ļ.	aka Coca Cola Foods; aka Nutrì-Foods International, Inc.)	360 S. Acacia Ave.	Eullastan	07021	l 1775 - E	1	Industrial Cleanup	Diesel, Gasoline Waste Oil, PCE	22 06745	117.00010	OCUCA	12/16/2010			Case Closed as		CAD000308239			T.,,,,,,,,	
-	incernational, inc.)	300 3. Acacia Ave.	ruilei (on	92651	1//3-6	z racres	Cleanup	waste Oil, PCE	33.86745	-117.89818	JUCHCA	12/16/2010	None	None	of 7/13/1987	Nothing	CAX000088104 CAL000213106			11/30/2010	16
6	Bimbo Bakeries USA (aka Airborne Express)	366 S. Acacia Ave.	Fullerton	92831	1782 - E	> 1 acres	DTSC- HWTS	Unknown	33.86736	-117.89817	None	9/13/2010	None	None	Nothing found		CAC001465936	0.005	211 - Halogenated Solvents	11/30/2010	11
7	Whitnon GMN (aka GMN Whitnon Spindell)	369 S. Acacia Ave.	Fullerton	92631	1737 - E	> 0.25 acres	DTSC- HWTS	Unknown	33.86756	-117.898292	None	9/13/2010	None	None	Nothing found	Nothing Found	CAL000111433 CAD983668088	Nothing Found	Nothing Found	11/30/2010	g.
	Right Connection Sportswear Company (aka Red	1	C11	02024	1750 5		DTCC INATC		22.06727	447.00005	Ī	0.140.1004.0				Nothing		0 1353	214 - Unspecified Solvent Mixture		-
8	Hat Society)	371 S. Acacia Ave.	Fullerton	92831	1760 - E	> 0.25 acres	DTSC-HWTS	Unknown	33.86/2/	-117.89826	None	9/13/2010	None	None	Nothing found	Nothing	CAL000318919	0.1353	Blank/Unknown	11/30/2010	12
9	S C Precision Molds, Inc.	419 S. Acacia Ave.	Fullerton	92631	1814 - E	> 0.25 acres	DTSC- HWTS	Unknown	33.86662	-117.89825	None	9/13/2010	None	None	Nothing found	Found		Nothing Found	Nothing Found	11/30/2010	9
10	WD & J Machine & Engineering	443 S. Acacia Ave.	Fullerton	92831	. 1848 - E	> 0.25 acres	DTSC- HWTS	Unknown	33.86634	-117.89824	None	9/13/2010	None	None	Nothing found	Nothing Found	CAL000200899	Nothing Found	Nothing Found	11/30/2010	q .
																Nothing			Thousand Thousand	11/30/2010	9 .
11	Khyber Foods Incorporated (aka Alnor Oil)	500 S. Acacia Ave.	Fullerton	92831	. 1965 - ESI	> 0.5 acres	OCHCH UST	Unknown	33.86568	-117.89815	None	9/13/2010	None	None	Nothing found	Found Last	CAC002609778	5.9605	Blank/Unknown	11/30/2010	11
	Wilson's Art Studio Inc (aka Solutions]								inspection on		8 195	343 - Unspecified Organic Liquid Mixture		
12	Unlimited)	501 S. Acacia Ave.	Fuilerton	92831	. 1947 - ESI	> 10 acres	OCHCA-HWSTS	ink Waste	33.86565	-117.89823	OCHCA	12/16/2010	None	None	Nothing found	3/6/09 Nothing	CAL000194220	11.9175	Blank/Unknown	11/30/2010	13
13	Yokohama Tire Corporation	601 S. Acacia Ave.	Fullerton	92831	2160 - ESI	> 20 acres	DTSC- HWTS	Unknown	33.86455	-117.89821	None	9/13/2010	None	None	Nothing found	_	CAP600928671	0.342	214 - Unspecified Solvent Mixture	11/30/2010	14
																	CAC002614456			ļ * 	
																		0.4215 1.817	214 - Unspecified Solvent Mixture 343 - Unspecified Organic Liquid Mixture	İ	
														ļ				1.1835	352 - Other Organic Solids		
																	CAL000308732	3.27835 1 6179	Blank/Unknown 214 - Unspecified Solvent Mixture	-	
								Waste Oil. Oil/Fuel								Last		2 0686	343 - Unspecified Organic Liquid Mixture]	
14	UPS Freight (aka Overnite Transportation)	650 S. Acacia Ave.	Fullerton	92831	2181 - FSF	> 10 acres		Filters, Waste Absorbent	33 86454	-117.89813	OCHCA	12/16/2010	Nane	None	Nothing found	inspection on	CAL000137824	0 2225 1.97761	352 - Other Organic Solids Blank/Unknown	11/30/2010	15
F										117.05015	- CITE-	127 107 2010	INOTIC	None	Nothing loans	Nothing	CALOUU137024	1.37701	Udiki Olikilowii	11/30/2010	13
15	City of Fullerton - Fire Department #3	700 S. Acacia Ave.	Fullerton	92831	2238 - ESE	1.5 acres	DTSC - HWTS	Unknown	33.86428	-117.89813	None	9/13/2010	None	None	Nothing found	Found	CAC002106240 CAD055703342	Nothing Found	Nothing Found	11/30/2010	10
	Plasticolor Molded Products Inc. (aka Plasticolor																CAD033703342 CAD980694715				
	Molded Products; aka Lokalex Inc.; aka Specialty Extrusion Corporation; aka Specialty Extrusion															Last	CAX000062539	0.0000	352 - Other Organic Solids	4	
16	Ltd.)	801 S. Acacia Ave.	Fullerton :	92831	2505 - SE	1.38 acres	OCHCA HWSTS	Waste Oil	33.86311	-117.898192	OCHCA	12/16/2010	None	None	Nothing found	inspection on 12/30/08	CAD981391873	0.8928 145.71	Blank/Unknown	11/30/2010	14
	Undercar Parts Corporation (aka Accent Plastics.				1216 -												CAD042405472	2.5	352 Other Oversia Saltda		
17	Inc.)	1206 E. Ash Ave.	Fullerton	92831	1	0.18 acres	DTSC - HWTS	Unknown	33.86559	-117.90677	None	12/16/2010	None	None	Nothing found	Nothing Found	1	2.5 2.5	352 - Other Organic Solids Blank/Unknown	11/3/2010	13
					1216 -			Nickle, Steel,									CAL000070279 CAL000007440	22.5473	Blank/Unknown		
18	Raymac Grinding Co.	1207 E. Ash Ave.	Fullerton	92831		0.18 acres	OCHCA HWSTS		33.86559	-117.90677	None	9/13/2010	None	None	Nothing found		CAL000007440 CAL000020845			11/3/2010	13
																	CAC001145672				
															Completed -		CAL000017239 CAL000259214				ļ
1.0	BC2 Environmental Rental (aka Avory Streech;	1242 5 Ash 1	e		1189 -		0.5116					0 /05 /==	<u> </u>		Case Closed as		CAD983616699		Blank/Unknown]	
19	aka Atlas Copco, Inc.; aka Prime Energy Systems)	1212 E. ASN AVE.	Fullerton	92631	55W	0.10 acres	OCHCA - LUST	Gasoline	33.86559	-117.90664	RWQCB	9/20/2010	None	None	of 9/20/2004	Found	CAC001065504		214 - Unspecified Solvent Mixture 211 - Halogenated Solvents	11/3/2010	16
																	1	9.3024	214 - Unspecified Solvent Mixture		
					1171 -											Last inspection on	CAD981452915		352 - Other Organic Solids Blank/Unknown		112
20	Kryler Corporation	1217 E. Ash Ave.	Fullerton	92831	ssw	0.08 acres	OCHCA HWSTS	Cadimium	33.86559	-117.90655	OCHCA	12/16/2010	None	None	Nothing found	4/7/10	CAX000116830			11/3/2010	16
21	Masco Sweepers, Inc. (aka Crenshaw Die and Manufacturing)	1223 E. Ash Ave.	Fuilerton	92831	1145 - SSW	0.17 acres	DTSC - HWTS	Unknown	33.86559	-117.90642	None	9/13/2010	None	None	Nothing found		CAL000055346 CAL000066892	Nothing Found	Nothing Found	11/3/2010	9
															samg round		CAC001381048		, realing / Sund	11/3/2010	3
	Performance Dip Braze (aka Santana Services;				1135 -												CAL000196840 CAL000350130				
22	aka Western Roto Engravers, Inc.)	1224 E. Ash Ave.	Fullerton	92831	ssw	0.05 acres	OCHCA HWSTS	No HW	33.86559	-117.90637	ОСНСА	12/16/2010	Archived	None	Nothing found	2/25/10	CAT080025018	Nothing Found	Nothing Found	11/3/2010	11
23	Security Signal Devices Inc. (aka Crenshaw Die & Manufacturing Corporation)	1227 E. Ash Ave.	Fullerton	92821	1128 - SSW	0.05 acres	DTSC - HWTS	Unknown	22 96550	-117.90633	None	9/13/2010	None	None	Nothing found		CAL000290149 CAL000020789	Nothing Found	Nothing Found	11/2/2012	4
									23.00337	711-20000	HOUSE	3/ 13/ 2010	NOTE	HOHE		Nothing	~~r000030103	Nouning Found	Mouning Found	11/3/2010	<u> </u>
24	Camarigg Automotive, Inc. (aka Nickolas Steel)	1229 E. Ash Ave.	Fullerton	92831	1116 - S	0.05 acres	DTSC - HWTS	Unknown	33.8656	-117.90628	None	9/13/2010	None	None	Nothing found	Found	CAL000011781	Nothing Found	Nothing Found	11/3/2010	9

Γ					-γ		1	In-tti		T	1			_				T	1		
			1		Distance			Detections of - Chemicals of					ļ					HAZNET Waste			
Мар				1	(feet) -			Concern (PCE, TCE	:.]		Overseeing							Types and		Drive-by	İ
Ref		1			Direction	Property Acres		perchlorate in			Regulatory	File Review	CERCLIS	Envirostor	GeoTracker	County HCA	1	Quantities (in		Date and	Site Screening or
No.	Site Name	Address	City	Zip	From FM8	(length x width)	Regulatory List	Groundwater)	Latitude	Longitude	Аделсу	Date	Status	Status	Status	Status	EPA ID#	tons)	HWTS California Waste Codes & Descriptions	Info	Reassessment Priority
								ĺ								Classias of	CAX000046219				
	Unitdesigned, Inc. (aka Euro West Inc.; aka Etl						OCHCA Industrial									Closed as of 5/7/1990; No	CAX000078154				
25	Garage; aka Programmed Composites)	1234 E. Ash Ave.	Fullerton	9283	L 1091 - S	0.34 acres	Cleanup	PCE, TCE	33.8656	-117.90615	ОСНСА	12/16/2010	None	None	Nothing found		CAC001242584	0.1	352 - Other Organic Solids	11/3/2010	14
	To the make the t											1,7,7,7				Nothing			ose other organic social	11/3/2010	
26	Southern California Trucking	1234 E. Ash Ave. Unit D	Fullerton	9283	l 1091 - S	0.05 acres	DTSC - HWTS	Unknown	33.8656	-117.90615	None	9/13/2010	None	None	Nothing found	Found	CAL000319351	Nothing Found	Nothing Found	11/3/2010	9
																	CAC002221033			-	
1																ĺ	CAC002578946 CAC002617427	Į			
				1												Nothing	CAC002617427 CAC002627950	5 364			
27	Commonwealth Elementary School	2200 E. Commonwealth Ave.	Fullerton	92632	3324 - ENS	9.70 acres	DTSC - HWTS	Unknown	33.87061	-117.893492	None	9/13/2010	None	None	Nothing found	_	CAC002603038	21.07	Blank/Unknown	11/30/2010	9
						1										Nothing				12,00,200	
28	California Almond Growers	324 S. Hale Ave.	Fullerton	92831	2738 - E		DTSC - HWTS	Unknown	33.86846	-117.89498	None	9/13/2010	None	None	Nothing found	}	CAX000062984	Nothing Found	Nothing Found	11/30/2010	9
29	Southern California Edison (aka California Almond Growers)	325 S. Hale Ave.	Fullerton	02022	12556 15	~ 1.5 acres	DTSC - HWTS	Unknown	33.86854	117 000000		0 /4 2 /2040		.		Nothing	CAC002593339				
25	Amond drowersy	323 3. Fiale Ave.	runerton	7203.	. [2550 - E	1.5 acres	DISC-HWIS	Олкломл	33,86834	-117.895592	None	9/13/2010	None	None	Nothing found	Nothing	CAD981369622	286.70954	Blank/Unknown	11/30/2010	12
30	Blue Line Foodservice Distribution	330 S. Hale Ave.	Fullerton	92831	. 2738 - E	~ 1 acres	DTSC - HWTS	Unknown	33.86842	-117.89498	None	9/13/2010	None	None	Nothing found		Unknown	Nothing Found	Nothing Found	11/30/2010	9
									1			1	 	<u> </u>			CAL000300124			12/30/2010	-
	Jaco Environmental (aka Corrugated Service			1.	1.					ļ	1		1			Nothing		1 309	343 - Unspecified Organic Liquid Mixture		
31	Orange, Inc.)	331 S. Hale Ave.	Fullerton	92831	. 2738 - E	1.5 acres	DTSC - HWTS	Unknown	33.86842	-117.89498	None	9/13/2010	None	None	Nothing found		CAL000200962	4.6018	Blank/Unknown	11/30/2010	14
							1	Condensor Oil.								Last		7.51025	744 Handdoodd Halana 2		7
32	Jaco Environmental, Inc.	331 S. Hale Ave. Ste A&B	Fullerton	92831	. 2738 - E	1.5 acres	OCHCA HWSTS		33,86842	-117.89498	OCHCA	12/16/2010	None	None	Nothing found	inspection on 5/5/10	CAL000200962	7.51825 16.5957	741 - Liquid with Halogen Organic Compound Blank/Unknown	11/30/2010	14
	· ·								12.000.2	221103100	-	10,10,000	1,10,110	IVOITE	Nothing touris	3,3,10	CALOUOZOOSOZ	0.1251	211 - Halogenated Solvents	11/30/2010	14
											-							0 126	214 - Unspecified Solvent Mixture		
											ĺ		Ì				İ	0 1751	342 - Organic Liquids with Metals		
																		0.374	343 - Unspecified Organic Liquid Mixture		
																		6 625 2.336	351 - Organic Solids with Halogens		
			-											O &M -Land		•			352 - Other Organic Solids 611 - Contaminated Soils from Site Clean-Up]
														Use				1 692	741 - Liquid with Halogen Organic Compound		.
				İ										Restrictions			CAD008323388	4180.33	Blank/Unknown		
	Ruan Transportation Corporation (aka Johnson													only	1		CAL000081128				
	Controls Battery Group, Inc.; aka Ruen Leasing Co.; aka Southern California Edison; aka J&V							DiI TCE 6 DCE						certified	Completed -		CAL000202865				
1	Cartage)	1550 E. Kimberly Ave.	Fullerton	92831	2073 - E	15 acres	OCHCA LUST	Diesel, TCE & PCE in Groundwater	33 86313	-117.90048	DTSC	12/16/2010	Archived	/Corrective	Case Closed as of 11/23/1987		CAC002612461 CAC002171313		Blank/Unknown	-	
	Specialty Extrusion Corporation (aka Al	LUSS EL MINISCHY AVE.	Tunciton	52051	2075-2	15 acres	OCHEA 2031	in Groundwater	33.80313	-117.50040	DISC	12/10/2010	Attilived	Action		Nothing	CAC002171313	0.45	352 - Other Organic Solids	11/3/2010	16
	McDougal)	1580 E. Kimberly Ave.	Fullerton	92831	2145 - ESE	~ 0.25 acres	DTSC - HWTS	Unknown	33.86314	-117.90002		9/13/2010	None	None	Nothing found	_	CAC002616022	Nothing Found	Nothing Found	11/3/2010	6
																		3 654	214 - Unspecified Solvent Mixture		
]					Active		Closure		2.244	343 - Unspecified Organic Liquid Mixture		
35	Orange County Metal Processing	1711 E. Kimberly Ave.	Eullerton	02021	2542 - ESE	1 5 perce	OCHCA HWSTS	Hakaawa	22 06215	-117.89798	RWQCB.	12/16/2010	None	Tiered	Assessment as of 11/7/1992	,	CA DOCA 4 4004 0	7.689 1.582	352 - Other Organic Solids		
33	orange county metal (rocessing	1711 L. Kimberry Ave.	Tullerton	32031	2342 - 636	1.5 acres	OCHCA HW313	OHKHOWH	33.00313	-11/.03/30	DISC	12/16/2010	None	Permit	OT 11///1992	9/23/10	CAD064449812	1.582	Blank/Unknown	11/3/2010	17
								VOC Polynuclear							Open - Site				Í		
							1	Aromatic							Assessment as						
36	PCA Metals	1723 E. Kimberly Ave.	Fullerton	92831	2415 - ESE	> 0.5 acres	GeoTracker	Hydrocarbons	33.86271	-117.908792	RWQCB	12/16/2010	None	None	of 6/1/2010		Unknown	Nothing Found	Nothing Found	11/3/2010	4
												İ				Last					
37	JB Hunt	2001 E. Kimberly Ave.	Fullerton	92831	2415 - ESE	> 0.5 acres	OCHCA HWSTS	Unknown	33.86271	-117.908792	OCHCA	12/16/2010	None	None	Nothing found	inspection on	CAC002571718	4 09	Blank/Unknown	11/3/2010	,
		,	1					Oil/Fuel Filters				,,,				~, ~~, ±0	/1/10		County Officiowif	11/3/2010	11
								Antifreeze											343 - Unspecified Organic Liquid Mixture		
			ļ				i I	Absorbent, Break	[-]									0.255	352 - Other Organic Solids		
38	Federal Express Corporation	2500 E. Kimberly Ave.	Eullarton	02024	5818 - E	5 74 acros	OCHCA HWSTS	Oil, Universal	22 05247	-117.885705	None	0/12/2010	Nor -	Nanc	Math: E	Nothing			741 - Liquid with Halogen Organic Compound		
	i caciai Express cai paradori	2000 C. KIRDERLY AVE.	rullerton	92031	2010 - E	5.74 acres	OCHCA HWS15	waste	33.6031/	-111.882/05	MOUG	9/13/2010		None Active /	Nothing found	round	CAL000005249	53.9244	Blank/Unknown	11/3/2010	14
						<u> </u>								State							
	Chicago Musical Instruments (aka United							*						Respond		Nothing					ĺ
39	Duralume Inc.)	350 S. Raymond Ave.	Fullerton	92831	938 - WSW	7.51 acres	EnviroStor	PCE, TCE, I, I-DCE	33.86791	-117.907092	DTSC	9/28/2010	None		Nothing found	Found	CAC002183273	Nothing Found	Nothing Found	12/1/2010	15
40	Telatemp Corporation	251 C Paumond Asso	Culter	02024	800 4604	0.5	DISC HILLE	1 Imlan	22 00704	147.00505		0/40/2020				Nothing	Ţ				
+	relatenty corporation	351 S. Raymond Ave.	runerton	34831	889 - WSW	0.5 acres	DTSC - HWTS	Unknown	33.86791	-117.90693	none	9/13/2010	None	None	Nothing found	round	CAC002595602	0.075	Břank/Unknown	12/1/2010	10
									.						Completed -		1				
]									Case Closed as	Nothing					[
41	Classic Marble Designs Inc. (aka Brecht Co.)	371 S. Raymond Ave.	Fullerton	92831	892 - WSW	0.5 acres	GeoTracker	Gasoline	33.86775	-117.90693	RWQCB	9/20/2010	None			- 1	CAC001223984	Nothing Found	Nothing Found	12/1/2010	10
				_						·							I		214 - Unspecified Solvent Mixture	1	
																		15.0552	343 - Unspecified Organic Liquid Mixture		
	Top Auto Repair (aka LG Knox Construction; aka			1													CAL000100088 CAC002575104	15.286	Blank/Unknown	⊣	ļ
	Terry's Automotive)	500 S. Raymond Ave.	Fullerton	92831	798 - SSW	0.18 acres	DTSC - HWTS	Unknown	33.86671	-117.907092	None	9/13/2010	None	None	Nothing found	- ;	CAL0002375104 CAL000284590			12/1/2010	15
									"						-	Nothing				12, 2, 2010	
43	Accurate Auto Performance	500 S. Raymond Ave. Ste B1	Fullerton	92831	798	0.18 acres	DTSC - HWTS	Unknown	33.86671	-117.907092	None	9/13/2010	None -	None	Nothing found	Found	CAL000207733	Nothing Found	Nothing Found	12/1/2010	9

							T					,					_				
					Distance			Detections of Chemicals of						}				LIA ZAICT MARKE			
Map					(feet) -			Concern (PCE TCE	<u>.</u> .		Overseeing							HAZNET Waste Types and		Drive-by	
Ref					Direction	Property Acres		perchlorate in	`		Regulatory	File Review	CERCLIS	Envirostor	GeoTracker	County HCA		Quantities (in		Date and	Site Screening or
No.	Site Name	Address	City	Zip	From FM8	{length x width}	Regulatory List	Groundwater)	Latitude	Longitude	Agency	Date	Status	Status	Status	Status	EPA ID#	tons)	HWTS California Waste Codes & Descriptions	Info	Reassessment Priority
						ļ											CAD983584459		214 - Unspecified Solvent Mixture		
														-			CAL000009329		342 - Organic Liquids with Metals	_	
	1														ļ		CAL000019783 CAL000190690	15	Blank/Unknown	_	
	 Tops Auto Body {aka K&N Automotive; aka														Ì	Last	CAL000190690				
	Trinity Auto Collision Inc.; aka Honda Car							Waste Oil Liquid								inspection on	CALBOOZOSOSO	2 12412	214 - Unspecified Solvent Mixture	_	
44	Specialty)	500 S. Raymond Ave. Unit C	Fullerton	92831	798 - SSW	0.18 acres	OCHCA HWSTS	Paint Waste	33.86671	-117.907092	OCHCA	12/16/2010	None	None	Nothing found	1 .	CAL000291186		352 - Other Organic Solids	12/1/2010	16
											-						CAL000094280		- <u>international de la constanta de la constan</u>		
45	Terry's Automotive. Inc. (aka Auto Hospital; aka	500 S D		00004			001101 1111070	l., .		447.00700	.					Nothing	CAL000218474			1	
45	Betos Auto Body & Paint, Inc.)	500 S. Raymond Ave. Unit D	Fullerton	92831	\28 - 22M	0.18 acres	OCHCA HWSTS	Unknown	33.866/1	-117.907092	None	9/13/2010	None	None	Nothing found		CAR000080614	Nothing Found	Nothing Found	12/1/2010	11
46	Beto s Paint & Body Inc.	500 S. Raymond Ave. Ste F	Fullerton	92831	798 - SSW	0.18 acres	DTSC - HWTS	Unknown	33.86671	-117.907092	None	9/13/2010	None	None	Nothing found	Nothing	CAL000223437	1.0944	214 - Unspecified Solvent Mixture 352 - Other Organic Solids	12/1/2010	12
		330 Si Naymona merote i	ranciton	152052	730 3311	0.20 00 03	Disc intris	GIRIOTII	33.00011	111.501052	. Hone	13/13/2010	TROTTE	MOUTE	140thing 10thio	Last	1CAL000223437	0.2	1552 - Other Organic Solids	12/1/2010	1 12
											1	1				inspection on					ŀ
47	Genesis Auto Body	500 S. Raymond Ave. Ste G	Fullerton	92831	798 - SSW	0.18 acres	OCHCA HWSTS	No HW	33.86671	-117.907092	ОСНСА	12/16/2010	None	None	Nothing found	2/24/10	Unknown	Nothing Found	Nothing Found	12/1/2010	9
								Ì									CAL000143885	0.3888	214 - Unspecified Solvent Mixture		
	Company Company]		}					1				Last	CAL000347193		· ·		
	5 Star Auto Care (aka Don s Auto Body; aka Specialized Machine & Metallizin)	500 S. Raymond Ave. Ste H	Eullerton	02931	709 - 55/4	0.18 acres	OCHCA HWSTS	No HW	22 96671	-117,907092	OCHCV	12/16/2010	None	Name	Nashiaa faad	1 '	CAL000347225 CAL000026201				
70	Specialized (viacinite & (vietalizzi))	300 3. Naymona Ave. Ste 11	rusiercon	32631	730-3374	0.10 acres	OCHCA HW313	INC HW	33,80071	-117.507052	. UCHCA	12/16/2010	None	None	Nothing found	12/3/09	CAL000026201	0.15	352 - Other Organic Solids	12/1/2010	13
	Topline Auto Collision LLC (aka Wheels Auto					1					}					1	CAL000224609 CAD982413536	V	552 Other Organic Strius	-	
1 1	Body & Paint Shop; aka Topline Paint & Body														1	Nothing	CAL000145857			İ	
49	Inc.; aka Leonardo's Paint & Body Shop)	500 S. Raymond Ave. #I	Fullerton	92831	798 - SSW	0.18 acres	OCHCA HWSTS	Unknown	33.86671	-117.907092	None	9/13/2010	None	None	Nothing found		CAL000353667			12/1/2010	11
	landar and Tarres N. A. A. A. A. A. A. A. A. A. A. A. A. A.] _			_															
	Inglewood Transmission Service Inc (aka Turret													İ							
50	La The Specialist; aka California Autobody & Paint; aka Tury'z Concepts Inc.)	500 S. Raymond Ave. Ste J	Fullerton	97921	798 - 5514/	0.18 acres	DTSC - HWTS	Unknown	33 96671	-117.907092	None	9/12/2010	None	None	Mothing f	Nothing	CA1000346733	Noth:	Nothing Found	40 (4 (0 - 1 -	1
33	sorry and rary a concepts inc.)	500 5. Raymona Ave. 5te J	r uner con	J2031	1,20-224	0.10 acres	DISC- HVVIS	CHKHOWII	1/800.00	-111.301092	INOIR	9/13/2010	None	None	Nothing found	round	CAL000346720 CAL000176657	Nothing Found	INOTHING FOUND	12/1/2010	10
																Nothing	CAX0000453770				
51	Larsco Corp. (aka Labeltech, aka Al Jiacomin)	503 S. Raymond Ave.	Fullerton	92831	1018 - SW	0.73 acres	DTSC - HWTS	Unknown	33.86662	-117.90692	None	9/13/2010	None	None	Nothing found	_	AC002661469	Nothing Found	Nothing Found	12/1/2010	11
, ,	OCB Reprographics (aka Fullerton Blueprint Co.								İ							Nothing					
52	Inc.)	528 S. Raymond Ave.	Fullerton	92831	1154 - SW	~ 0.25 acres	DTSC - HWTS	Unknown	33.86596	-117.90691	None	9/13/2010	None	None	Nothing found	Found	CAL000157542	Nothing Found	Nothing Found	12/1/2010	10
																Last		1			
53	E.J. Whitney Co, Inc.	529 S. Raymond Ave.	Eullorton	02021	1154 . \$\M	0.73 acres		Waste Acetone Q- SOL300 Solvent	1	-117.90691	OCHCV	12/16/2010	Nana	Nama	Nashing found	inspection on	C41 0000000045	4.000			
33	LS. Writing Co, tik.	329 3. Raymond Ave.	Fullerton	92031	1134 - 344	0.73 au es	OCHCA HW313	SOLSOO SOIVEIR	33.60336	-117.30031	OCHCA	12/16/2010	None	None	Nothing found	Nothing	CAL000089845	1.692	214 - Unspecified Solvent Mixture	12/1/2010	14
54	Semaan Printing Co, Inc.	535 S. Raymond Ave.	Fullerton	92831	1198 - SW	~ 0.25 acres	DTSC - HWTS	Unknown	33.86578	-117.90691	None	9/13/2010	None	None	Nothing found		CAD983652686	Nothing Found	Nothing Found	12/1/2010	13
		·													gg.	Nothing				12,1,2010	1 13
55	Faber Laboratories	539 S. Raymond Ave.	Fullerton	92831	1228 - SW	~ 0.25 acres	DTSC - HWTS	Unknown	33.86565	-117.9069	None	9/13/2010	None	None	Nothing found	Found	CAD981672793	Nothing Found	Nothing Found	12/1/2010	12 .
															•	Last		11 15140	Blank/Unknown		
56	Bavarian Autotech s (aka Bavarian Auto Tech)	551 S. Raymond Ave.	Fullarton	02021	1264 514	0.11 acres		Waste Oil. Waste Antifreeze	33 06551	-117.9069	OCUCA	12/15/2010	N		Nanklata Carasi			11.10840	343 - Unspecified Organic Liquid Mixture	վ <i></i>	
30	Davarian Autotech S (aka Davarian Auto Tech)	1551 5. Raymond Ave.	runerton	9203I	1204 - 344	0.11 acres	OCHCA RW313	Antineeze	33.66331	-117.9069	OCHCA	12/16/2010	None	None	Nothing found	8/19/10	CAL000017247 CAL000023015			12/1/2010	13
																	CAL000074084				
				1	1396 -												CAL000087735				
57	Acme Door Closers	600 S. Raymond Ave.	Fullerton	92831	 	0.09 acres		Unknown	33.86503	-117.9069	None	9/13/2010	None	None	Nothing found	Found	CAL000208327	Nothing Found	Nothing Found	12/1/2010	11
			L		1288 -			l								Nothing				ĺ	
58	CCJ Corporation	602 S. Raymond Ave.	Fullerton	92831		~ 1 acres		Unknown	33.86549	-117.906992	None	9/13/2010	None	None	Nothing found		CAL000260864	Nothing Found	Nothing Found	12/1/2010	11
59	Lone Star Termite and Pest Control Inc.	606 S. Raymond Ave.	Fullerton	92831	1299 - SSW	~ 1 acres		Unknown	33.86545	-117.906992	None	9/13/2010	None	None	Nothing found	Nothing Found	CAL000200047	Nothing Court	Mathiag Found	13/1/2010	
<u> </u>	The second of th	or majoriority reco		54051		2 20163		- Innovill	22,00343	11.300332		2/ 13/ 2010	reuilE	140116		Last	UNLUUUZ3034/	Nothing Found	MOUNTE FOUND	12/1/2010	11
					1222 -		ĺ									inspection on					İ
60	United States Spring & Stamping CO, Inc.	615 S. Raymond Ave.	Fullerton	92831		0.23 acres	OCHCA HWSTS	Waste Nitric Acid	33.86489	-117.90689	OCHCA	12/16/2010	None	None	Nothing found		CAL000316333	Nothing Found	Nothing Found	12/1/2010	9
	Save Barro Barro	222.5			1445 -			l						 		Nothing					
61	Same Day Cylinder	619 S. Raymond Ave.	Fullerton	92831	ISSW	~ 0.25 acres		Unknown	33.86485	-117.90689	None	9/13/2010	None	None	Nothing found		CAL000001181	0.2	Blank/Unknown	12/1/2010	9
														1			CAX000066431				
										<u> </u>	1			1]]		CAC002645795 CAL000349764				
										Ì]		CAP0000349764 CAP0000002065				
]												CAL000135894	3.0862	Biank/Unknown	╡ !	
	Mesa Cold Storage Ltd (aka Frozsun Food; aka				l			Oil Compressor				ļ				Last	CAD983663824	1.045	Blank/Unknown		
	New West Foods, aka AmeriCold Logistics; aka	700 5 8			1678 -			Filters, Universal		 					1		CAL920525562		741 - Liquid with Halogenated Organic Compound	_]!	ļ
62	Cleugh's Rhubarb Company; aka AmeriCold)	700 S. Raymond Ave.	Fullerton	92831	22M	3.12 acres	OCHCA HWSTS	vvaste	33.86407	-117.90687	UCHCA	12/16/2010	None	None	Nothing found		CAL000257463	0.396	214 - Unspecified Solvent Mixture	12/1/2010	16
					1805 -			Recycle Oil Oil							1	Last inspection on		ĺ		.	,
63	Spacer Connection, Inc.	711 S. Raymond Ave. Ste A	Fullerton	92831	ı	0.25 acres	OCHCA HWSTS	· ·	33.86366	-117.90686	OCHCA	12/16/2010	None	None	Nothing found		CAD982439861	1.6258	741 - Liquid with Halogen Organic Compound	12/1/2010	10
		,		1												Last				25/1/5010	. 10
					1805 -											inspection on		10.0474	Blank/Unknown		
64	Performance Envelope Co.	711 S. Raymond Ave. Unit B	Fullerton	92831	SSW	0.25 acres	OCHCA HWSTS	Waste Ink/Solvent	33.86366	-117.90686	OCHCA	12/16/2010	None	None	Nothing found			0.25839	741 - Liquid with Halogen Organic Compound	12/1/2010	15
					1960										1		CAL000279460				
65	Roys Transmission Service	715 S. Raymond Ave.	Fullerton	92831	1860 - ISSW	0.22 acres	OCHCA HWSTS	Waste Oil	33 86340	-117.90686	OCHCA	12/16/2010	None	None	Nothing found	inspection on	CAL000014707	1 6463	Błank/Unknown	13/1/2010	43
									,50.50545	22,150000	30.765	,,,		.,0116	A COUNTY		CAL000014707 CAL000305311		Blank/Unknown	12/1/2010	12
																ľ			Blank/Unknown		
											1					ł			214 - Unspecified Solvent Mixture		i
											Ī						I		343 - Unspecified Organic Liquid Mixture		
	Terra Universal, Inc. (aka California Shirt Sales,	200 C Paymond Avo	Eulforte-	02021	2109	4 68 35505	OCUCA UNICE	Unknowe	22 06777	117 00cec	None	0/12/2010	None	No=-	1		CAL000068048		352 - Other Organic Solids	_	
00	Moore Business Forms)	800 S. Raymond Ave.	Fullerton	უ283I	۷۷۷	4.68 acres	OCHCA HWSTS	UTKHOWE	33.662/3	-117.90686	INORE	9/13/2010	попе	None	Nothing found	round	CAŁ000305311	3.979	Blank/Unknown	12/1/2010	17

	1	1		1	<u> </u>		1	Detections of	1	1	Т	Т	· · · · · · · · · · · · · · · · · · ·	-r		· · · · · · · · · · · · · · · · · · ·	<u> </u>				
					Distance			Detections of Chemicals of										HAZNET Waste			
Map					(feet) -			Concern (PCE TCE	i.		Overseeing							Types and		Drive-by	ļ
Ref No.	Site Name	Addraga	City.	71	Direction	1 ' '	0	perchlorate in	1		Regulatory	File Review	CERCLIS	Envirostor	GeoTracker	County HCA		Quantities (in		Date and	Site Screening or
INO.	2)te Mame	Address	City	Zip	2132 -	(length x width)	Regulatory List	Groundwater)	Latitude	Longitude	Agency	Date	Status	Status	Status	Status Nothing	EPA ID#	tons)	HWTS California Waste Codes & Descriptions	Info	Reassessment Priority
67	Storage Outlet Self Storage	900 S. Raymond Ave.	Fullerton	9283		1.19 acres	DTSC - HWTS	Unknown	33.86271	-117.906992	None	9/13/2010	None	None	Nothing found	~	CAC002644807	Nothing Found	Nothing Found	12/1/2010	10
	Rayne Water Conditioning (aka Pacific Industrial	·		1			·				T	1,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			1	Nothing	C 10002044007	Trouming round	Nothing Found	12/1/2010	10
68	Water System)	1702 E. Rosslynn Ave.	Fullerton	9283	1 2304 - ES	1.67 acres	DTSC - HWTS	Unknown	33.86402	-117.8981	None	9/13/2010	None	None	Nothing found	Found	CAL000122318	Nothing Found	Nothing Found	11/3/2010	10
							<u>.</u>	-								4	ĺ	4 779	214 - Unspecified Solvent Mixture		
69	Orange County Paint	1710 E. Rosslynn Ave.	Fullerton	9283	1 2305 - ES	< 1.5 acres	DTSC - HWTS	Unknown	33.86401	-117.898101	None	9/13/2010	None	None	Nothing found	Nothing	CAL000040641	0.2 1.0756	352 - Other Organic Solids Blank/Unknown	12/2/2010	17
	,	1		1						1	T. C.	3) 13/2010	, and	Tiered	Hoding today	Tound	CAL000040041	0.34	343 - Unspecified Organic Liquid Mixture	11/3/2010	17
	•			1				l		Ì			Ĭ	Permit;		ĺ		10.4178	352 - Other Organic Solids	ĺ	
	PCA Industries, Inc. (aka PCA Metal Finishing				ļ		<u> </u>	Chlorinated Solvents (PCE						Refer to		N1.	CAD038682522	429.497	Blank/Unknown		
70	Inc.; aka PCA Industries, LLC.)	1726 E. Rosslynn Ave.	Fullerton	9283	1 2363 - ESI	> 2 acres	EnviroStor	TCE)	33.86402	-117.89785	DTSC	9/28/2010	None	RWQCB; Active	Nothing found	Nothing	CAX000013672			11/2/2010	10
								<u> </u>			12.00	3,20,2020	None	J NOCITE	Trouming round	T Outlo	C-0000013072			11/3/2010	16
]		[
									ļ						Completed -						
				İ					Í						Case Closed as		CAC000232969				1
						1		Gasoline, Volatile						Active/	of 4/9/1990; Open - Site						
	Metałclad Insulation Corporation (aka Khyber			1 .			GeoTracker	Organic			DTSC		1	Corrective	Assessment as	Nothing	-	54 0	Blank/Unknown		
71	Foods, Inc.)	1818 E. Rosslynn Ave.	Fullerton	9283:	1 2594 - ESI	0.55 acres	LUST	Compounds	33.86404	-117.89689	RWQCB	9/20/2010	None	Action	of 5/5/2010	Found	CAR000185801	0.187	343 - Unspecified Organic Liquid Mixture	11/3/2010	7
									ļ										214 - Unspecified Solvent Mixture		
	St Hart Container Corporation Division of													Tiered		Nothing	CAL000043359		352 - Other Organic Solids Blank/Unknown]
	Subclipse (aka St. Hart Container Corporation)	1901 E. Rosslynn Ave.	Fullerton	9283	1 2811 - ESE	7.07 acres	DTSC - HWTS	Unknown	33.86406	-117.89603	DTSC	9/28/2010	None	Permit	Nothing found	-	CAD983662008	163.57	Bianky Unknown	11/3/2010	16
	,,			1		1						, ., .,		1			2.200002000	0 3544	342 - Organic Liquids with Metals	11/3/2010	10
-]		Floroscent Lamp					-		ļ	Last			352 - Other Organic Solids		
72	Communication Co. John Communication (Co.)	1011 F. Barahara Ara	F	0202				Starch and Waste							ĺ	inspection on	CAD983643479	23.4311	Blank/Unknown		1
73	Corru-Kraft, Co. (aka Corru-Kraft, Inc.)	1911 E. Rosslynn Ave.	Fullerton	92833	1 2837 - ESI	> 5 acres	OCHCA , UST	Water	33.86406	-117.89593	OCHCA	12/16/2010	None	None	Nothing found	2/2/10	CAC000211961			11/3/2010	16
		}											İ		1		CAC002213425 CAL000161364				
																	CAC001508024				
															<u> </u>			1.4975	Blank/Unknown		
]				214 - Unspecified Solvent Mixture		
			1											ļ				0.0075	343 - Unspecified Organic Liquid Mixture	ļ	i
	YRC Enterprise Services DBA USF Reddaway (aka							Heavy Metal									CAL000316180 CAD008289449		352 - Other Organic Solids Blank/Unknown	_	
	EDO Corp. Western Div.; aka USF/Reddaway; aka						OCHCA Industria	1 '								Closed as of			Blank/Unknown	\dashv	1
74	Gulton Industries; aka Bud's Delivery Inc.)	300 S. State College Blvd.	Fullerton	92831	L 4385 - E	4.11 acres	Cleanup	Plating), PCE	33.86813	-117.88953	OCHCA	12/16/2010	None	None	Nothing found				Blank/Unknown	11/30/2010	15
															l f		CAC002633320				
									1					i					Blank/Unknown	i l	
]	Nothing			343 - Unspecified Organic Liquid Mixture 352 - Other Organic Solids		
75	Kairak aka Don Green's Sales Inc.	500 S. State College Blvd.	Fuilerton	92831	L 4409 - E	7.68 acres	DTSC - HWTS	Unknown	33.86689	-117.88951	None	9/13/2010	None	None	Nothing found		CAD064480858		741 - Liquid with Halogen Organic Compound	11/30/2010	15
																Nothing	CAD981432347				
/6	Fullerton iNDL Park (aka A L S Corporation)	501 S. State College Blvd.	Fullerton	92831	. 4409 - E	~ 2 acres	DTSC - HWT\$	Unknown	33.86689	-117.88951	None	9/13/2010	None	None	Nothing found		CAD981650955	Nothing Found	Nothing Found	11/30/2010	8
77	OP & F Trust & Rreef Management	541 S. State College Blvd.	Fullerton	92831	4423 - E	> 1 acres	DTSC - HWTS	Unknown	33.8666	-117.8895	None	9/13/2010	None	None	Nothing found	Nothing Found	CAC001384280	Nothing Found	Nothing Found	11/20/2010	
				1		1			40.0000	447.0033		3/13/2010	None	ITONIE	T .	Last	CAL000257849		Blank/Unknown	11/30/2010	8
																inspection on				7	
78	Rozak Engineering Inc. aka Qualitask inc.	556 S. State College Blvd.	Fullerton	92831	4428 - E	> 1 acres	OCHCA HWSTS	Waste Oil, Used Oil	33.86649	-117.8895	OCHCA	12/16/2010	None	None	Nothing found		CAL000338819			11/30/2010	8
79	Alcoa Global Fasteners, Inc.	561 S. State College Blvd.	Fullerton	92831	4429 - E	~ 0.5 acres	DTSC - HWTS	Unknown	33 86646	-117.8895	None	9/13/2010	Nana	None	Nothing found	Nothing	CA1000377334	0.1345	214 - Unspecified Solvent Mixture	1.1/22/22/2	_
	· · · · · · · · · · · · · · · · · · ·	Social conego bira.	1 01101 011	32.00.	17725	0.5 dci es	D15C 114415	Olikilowii	33.50040	-117.8833	None	3/13/2010	Noise	None		Nothing	CAŁ000277221	0.1245	214 - Unspecified Solvent Mixture	11/30/2010	7
80	Sprint Printing Inc.	570 S. State College Blvd.	Fullerton	92831	. 4433 - E	0.5 acres	DTSC - HWTS	Unknown	33.86639	-117.8895	None	9/13/2010	None	None	Nothing found I	_	CAL000035196	Nothing Found	Nothing Found	11/30/2010	7
	MORE Designated and the second second	E-70 6 61 1 6 11 61 1															CAD094121845				
81	MOPC Printing (aka Christian Printing Service)	579 S. State College Blvd.	Fullerton	92831	. 4436 - E	0.5 acres	DTSC - HWTS	Unknown	33.86633	-117.8895	None	9/13/2010	None	None	Nothing found i		CAL000146010	1.413	214 - Unspecified Solvent Mixture	11/30/2010	12
82	Accurate Industrial Construction Inc.	580 S. State College Blvd.	Fullerton	92831	. 4437 - E	0.5 acres	DTSC - HWTS	Unknown	33.86631	-117.8895	None.	9/13/2010	None	None	Nothing found F	Nothing Found	CVIUUUSEESSE	Nothing Found	Nothing Found	11/20/2010	<u>"</u>
		200000		1	1				55.50051			2) 23/ 2010	.10110	140115		Nothing	CACOOD333383	Mouning roung	Nothing Found	11/30/2010	7
83	Soma Magnetics Corporation	585 S. State College Blvd.	Fullerton	92831	4438 - E	0.5 acres	DTSC - HWTS	Unknown	33.86629	-117.8895	None -	9/13/2010	None	None	Nothing found F		CAL000304015	0.15	352 - Other Organic Solids	11/30/2010	7
C.4	Change France Control	FOM C CY . C N - T' .		0000											0	Nothing					
64	Circuit Image Systems	591 S. State College Blvd.	rullerton	92831	4441 - E	> 0.5 acres	DTSC - HWTS	Unknown	33.86624	-117.8895	None	9/13/2010	None	None	Nothing found F	ound			Nothing Found	11/30/2010	8
	Juniors Professionals Ironwork (aka Remtech									į						Nothing	CAL000027703		343 - Unspecified Organic Liquid Mixture Blank/Unknown		
	-	597 S. State College Blvd.	Fullerton	92831	4443 - E	> 0.5 acres	DTSC - HWTS	Unknown	33.8662	-117.8895	None	9/13/2010	None	None	Nothing found F	~	CAL000027703 CAL000338720		ыалу отмірин	11/30/2010	10
																	CAD981570773		Name and Alexandria	22, 30, 2010	10
86	Nordstrom, Inc.	601 S. State College Blvd.	Fullerton	92831	4447 - ESE	0.5 acres	DTSC - HWTS	Unknown	33.86617	117.88949	None	9/13/2010	None	None	Nothing found F			Nothing Found	Nothing Found	11/30/2010	7
87	Nelson-Keystone Inc. (aka Rreef management)	623 S. State College Blvd.	Euilostos	92021	MASE EST	O E norce	DTCC _ UIATTC	Unimove	22 06004	117 00040	Nama		.	Mana			CAC001029280				
	Picture This (aka Precision Mold Base	023 3. State College BIVO.	runerton	34851	14430 - ESE	> 0.5 acres	DTSC - HWTS	UUKNOWB	55.866U1 -	117.88949	none	9/13/2010	None	None	Nothing found F			Nothing Found	Nothing Found	11/30/2010	7
	Corporation; aka OP&F Trust & Rreef] [[1			CAX000225789				ļ
	Management Co.)	631 S. State College Blvd.	Fullerton	92831	4460 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86595	117.88949	None .	9/13/2010	None	None	Nothing found F		CAC002302521).102	343 - Unspecified Organic Liquid Mixture	11/30/2010	8
														/###	- 1		ı).1	352 - Other Organic Solids		
	Southern California Precision (aka Fullerton	C41 C Chaba C-11 D1 1	F11	0202	446		DTEE LIVES		22.25-5-	447.000	.		_		I .		CAL000335575		Blank/Unknown	_	
89	Industrial Park)	641 S. State College Blvd.	Fullerton	92831	4464 - ESE	1 acres	DTSC - HWTS	Unknown	33.86588	117.88949	None	9/13/2010	None	None I	Nothing found F		CAC002565473		214 - Unspecified Solvent Mixture	11/30/2010	13
											İ			-			CAL000031559 CAL000214333 !		211 - Halogenated Solvents 214 - Unspecified Solvent Mixture	-	}
· 1	· ·	•	1	r	,	, ,		'	i	ı	ı	I	I	1	1	l	- 1E000214333	/,UUT	224 Onspecimen solvent ivitature		1

Map Ref No.	Site Name	Address	City	Zip	Distance (feet) - Direction From FM8	Property Acres (length x width)	Regulatory List	Detections of Chemicals of Concern (PCE TCE perchlorate in Groundwater)	Latitude	Longitude	Overseeing Regulatory Agency	File Review Date	CERCLIS Status	Envirostor Status	GeoTracker Status	County HCA Status	EPA ID#	HAZNET Waste Types and Quantities (in tons)	HWTS California Waste Codes & Descriptions	Drive-by Date and Info	Site Screening or Reassessment Priority
																	CAL000031559 CAL000214333	0.44	211 - Halogenated Solvents 214 - Unspecified Solvent Mixture		neassessment Horizy
90	Future Tattoo & Body Piercing (aka Perfect Coat Inc.; aka Pink Tiger)	645 S. State College Blvd.	Fullerton	92831	4465 - ESE	0.55 acres	DTSC - HWTS	Unknown	33.86585	-117.88949	None	9/13/2010	None	None	Nothing found	Nothing Found	CAC002319681 CAL000031559	0.44	211 - Halogenated Solvents	11/30/2010	12
91	Native Gear	651 S. State College Blvd.	Fullerton	92831	4469 - ESE	~ 0.5 acres	DTSC - HWTS	Unknown	33.86581	-117.88949	None	9/13/2010	None	None	Nothing found		CAL000205320	0.0416	741 - Liquid with Halogen Organic Compound	11/30/2010	11
92	Classic Silk Screen Design	651 S. State College Blvd. Unit 15	Fullerton	92831	4469 - ESE	> 1 acres	DTSC - HWTS	Unknown	33.86581	-117.88949	None	9/13/2010	None	None	Nothing found	}	CAL000205320	0.0416	741 - Liquid with Halogen Organic Compound	11/30/2010	8
93	AC Alternator & Starter Shop	651 S. State College Blvd. #17	Fullerton	92831	4469 - ESE	> 1 acres	DTSC - HWTS	Unknown	33.86581	-117,88949	None	9/13/2010	None	None	Nothing found	Nothing Found Nothing	CAL000100087	Nothing Found	Nothing Found	11/30/2010	11.
94	Garner Grinding	655.S. State College Blvd.	Fullerton	92831	4471 - ESE	> 1 acres	DTSC - HWTS	Unknown	33.86578	-117.88949	None	9/13/2010	None	None	Nothing found	1 "	CAL000177208	Nothing Found	Nothing Found	11/30/2010	8
95	Petrusse-Norris Painting	655 S. State Coilege Blvd. #27	Fullerton	92831	4471 - ESE	> 1 acres	DTSC - HWTS	Unknown	33.86578	-117.88949	None	9/13/2010	None	None	Nothing found		CAL000170665	7.4926	214 - Unspecified Solvent Mixture Blank/Uknown	11/30/2010	14
96	Superior Lift	655 S. State College Blvd. No. 31	Fullerton	92831	4471 - ESE	> 1 acres	DTSC - HWTS	Unknown	33.86578	-117.88949	None	9/13/2010	None	None	Nothing found		CAD983601766 CAC002592116	Nothing Found	Nothing Found 343 - Unspecified Organic Liquid Mixture	11/30/2010	8
97	Ropack Corp	660 S. State College Blvd.	Fullerton	92831	4473 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33,86574	-117.88949	None	9/13/2010	None	None	Nothing found	Nothing	CAC002557898 CAC000764400	0 187	Blank/Unknown 343 - Unspecified Organic Liquid Mixture Blank/Unknown	11/20/2010	9
98	Anglin's Instrument Repair (aka Industrial Starters)	663 S. State College Blvd.			4475 - ESE		DTSC - HWTS	Unknown		-117.88949		9/13/2010				Nothing		Nothing Found		11/30/2010	7
99	G.P. Precision	667 S. State College Blvd.	Fullerton	92831	4477 - ESE	> 0.5 acres	DTSC - HWTS	Unknown		-117.88949	1		None			Nothing		Nothing Found		11/30/2010	7
100	Mike Harrison Construction, Inc.	667 S. State College Blvd. #79	Fullerton	92831	4477 - ESE	> 0.5 acres	DTSC - HWTS	Unknown		-117.88949	<u> </u>		None			Nothing		Nothing Found		11/30/2010	7 .
101	Airsoft Advantage (aka Machine Tool Factory)	679 S. State College Blvd.	Fullerton	92831	4485 - ESE	0.51 acres	DTSC - HWTS	Unknown	33.86561	-117.88948	None	9/13/2010				Nothing		Nothing Found		11/30/2010	7
102	Awnings by Russ (aka Trico Realty, Inc.)	689 S. State College Blvd.	Fullerton	92831	4490 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86555	-117.88948	None	9/13/2010	None			Nothing		Nothing Found		11/30/2010	8
103	Micr Comp, Inc.	689 S. State College Blvd. #A	Fullerton	92831	4490 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86555	-117.88948	None	9/13/2010	None		Nothing found	Nothing		Nothing Found		11/30/2010	7
104	Dzine Fab	689 S. State College Blvd. Ste F	Fullerton	92831	4490 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86555	-117.88948	None	9/13/2010	None	None	Nothing found	Nothing Found		Nothing Found	·	11/30/2010	7
105	Advanced Machine & Tool	699 S. State College Blvd. #F	Fullerton	92831	4495 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86547	-117.88948	None	9/13/2010	None	None	Nothing found	Nothing Found	CAL000081103	Nothing Found	Nothing Found	11/30/2010	7
106	Jarreau Signs	699 S. State Coilege Blvd. Ste I	Fullerton	92831	4495 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86547	-117.88948	None	9/13/2010	None	None	Nothing found	Nothing Found	CAL922045947	0.0498	741 - Liquid with Halogenated Organic Compound	11/30/2010	7
107	Juniors Professional Iron	699 S. State College Blvd. Unit K	Fullerton	92831	4495 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86547	-117.88948	None	9/13/2010	None	None	Nothing found	Nothing Found	CAD983663550	Nothing Found		11/30/2010	7
108	College Business Park (aka Crico-HST Associates)	701 S. State College Blvd.	Fullerton	92831	4497 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86546	-117.88948	None	9/13/2010	None	None	Nothing found	Nothing Found			352 - Other Organic Solids Blank/Unknown	11/30/2010	9
	Trico Rents (aka Javier Ornamental; aka Lympus Prints; aka Typewriter M D's)	707 S. State College Blvd.	Fullerton	92831	4500 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86541	-117.88948	None	9/13/2010	None	None I	Nothing found	Nothing	CAC459300005 CAL000117347 CAX000205757	Nothing Found	Nothing Found	11/30/2010	8
110	Summit Event Productions	707 S. State College Blvd. Ste A	Fullerton	92831	4500 - ESE	> 0.5 acres	DTSC - HWTS			-117.88948		9/13/2010				Nothing		Nothing Found		11/30/2010	7
111	Perfect Coat, Inc.	707 S. State College Blvd. Unit D	Fullerton	92831	4500 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86541	-117.88948	ĺ	9/13/2010				Nothing	CAR000178723		343 - Unspecified Organic Liquid Mixture	11/30/2010	7
112	American Diversifed Silver (aka Bright Polishing Inc.)	717 S. State College Blvd.	Fullerton	92831	4505 - ESE	> 0.5 acres	DTSC - HWTS	Unknown	33.86534	-117.88948		9/13/2010				Nothing	CAX000066431	Nothing Found		11/30/2010	8
112	A D S Gold, Inc.	747 LC Chata College Blod	F. Illantan	02024	4505 505	0.5	DTGG LINLTS									Nothing	CAX000067611	1.4	352 - Other Organic Solids		
		717-J S. State College Blvd. 717 S. State College Blvd. # K			4505 - ESE					-117.88948					1	Nothing	CAD981446636		Blank/Unknown	11/30/2010	10
		727 S. State College Blvd. # N			4505 - ESE 4512 - ESE				ĺ							Nothing	CAL000007131	Nothing Found		11/30/2010	7
	·	727 S. State College Blvd, Unit A			4512 - ESE		DTSC - HWTS	<u> </u>		-117.88948						Nothing	CAL000321184			11/30/2010	7
		727 S. State College Blvd. Ste C	Ť		4512 - ESE		DTSC - HWTS			117,88948						Nothing	CAL000284819		343 - Unspecified Organic Liquid Mixture	11/30/2010	7
		733 S. State College Blvd.			4512 - ESE							0/13/2010				Nothing	CAD00321184			11/30/2010	7
		733 S. State College Blvd. #98			4516 - ESE					117.88948		0/13/2010 I 0/13/2010 I	ĺ		lothing found F Nothing found F	Nothing	CAD981379449		Blank/Unknwon	11/30/2010	7
		737 S. State College Blvd.			4519 - ESE					117.88948		7/13/2010 1 1/13/2010 1	***	***		Nothing	CAL000163527 CAL000062031			11/30/2010	7
		743 S. State College Blvd.			4522 - ESE			7		117.88948						Vothing	CAD981419229			11/30/2010	7
		747 S. State College Blvd.			4524 - ESE					117.88948				7		Nothing	CAL000017268			11/30/2010	7
		751 S. State College Blvd.			4527 - ESE				```							Nothing		Nothing Found		11/30/2010	7
	AES Electronics Recycling . Inc. (aka Bright															(CAL000303160 CAL000185248 CAX000066431	g v e enem	Grant Control of the	22,00,2010	,
124	Polishing, Inc.; aka Advanced E-Waste Solutions)	751 S. State College Blvd. Ste. 44	Fullerton !	92831	4527 - ESE	> 0.5 acres	OTSC - HWTS	Unknown 3	33.86508 -	117.88948	None 9	/13/2010 N	Vone I	None N	lothing found F	ound (UW00000050	Nothing Found	Nothing Found	11/30/2010	7

					Dietara			Detections of			T										
Map					Distance (feet) -			Chemicals of Concern (PCE, TCE			Overseeing							HAZNET Waste Types and		Date L.	
Ref					Direction	Property Acres		perchlorate in			Regulatory	File Review	CERCLIS	Envirostor	GeoTracker	County HCA		Quantities (in		Drive-by Date and	Site Screening or
No.	Site Name	Address	City	Zip	From FM8	(length x width)	Regulatory List	Groundwater)	Latitude	Longitude	Agency	Date	Status	Status	Status	Status	EPA ID#	tons).	HWTS California Waste Codes & Descriptions	Info	Reassessment Priority
125	OneTech Circuit Inc.	753 S. State College Blvd. Unit 30	Fullerton	92831	. 4529 - ESE	0.5 acres	DTSC - HWTS	Unknown			None	9/13/2010	None .	None	Nothing found	Nothing	C4D001405062	Nothing Found	Nothing Farmed	11/20/2010	_
1		700 01 01 11 0 11 0 11 0 11 0 11 0 11 0	- Lanciton	32002	1023 202	0.5 20165	2130 11413	Onkilowii	1		None	9/13/2010	ivone .	Notte	Nothing round	Nothing	CAD962485965	INDUME FOUND	Nothing Found	11/30/2010	7
126	Tiny's Forklift	759 S. State College Blvd.	Fullerton	92831	4532 - ESE	0.5 acres	DTSC - HWTS	Unknown	33.86502	-117.88948	None	9/13/2010	None	None	Nothing found	1 -		Nothing Found	Nothing Found	11/30/2010	7
127	Pho Ellie (aka Fortress Foto Finishing; aka State College Quickprint)	765 S. State College Blvd.	Fullerton	92831	. 4537 - ESE	0.5 acres	DTSC - HWTS	Unknown	33 86407	-117.88948	None	9/13/2010	None	None	Nothing found	Nothing	CAD983638008	Nothing Found.			_
		The state of the s	- unununu	32001	7007 202	0.5 00103	Disc mins	OH(HOW()	33.00437	-117.00340	None	3/13/2010	Mone	None	Notaling round	Nothing	CAD392993183	0.8428	352 - Other Organic Solids	11/30/2010	7
128	Trico Realty	765 S. State Coilege Blvd. Unit C	Fullerton	92831	4537 - ESE	0.5 acres	DTSC - HWTS	Unknown	33.86497	-117.88948	None	9/13/2010	None	None	Nothing found	Found	CAC002576167		Blank/Unknown	11/30/2010	9
																Last					
129	Creative Machining, Inc.	765 S. State College Blvd. Ste D	Fullerton	92831	4537 - ESE	0.5 acres	OCHCA HWSTS	Unknown	33.86497	-117.88948	OCHCA	12/16/2010	None	None	Nothing found	inspection on	CAL000276594	0.25	352 - Other Organic Solids	11/30/2010	7
			<u> </u>	T									1		Troumg round	1,70,20	C. (2502) 0554	87.8782	Blank/Unknown	11/30/2010	,
								PCE, TCE, Other								Closed as of			211 - Halogenated Solvents		
							OCHCA HWSTS	Chlorinated Hydrocarbons,						Refer: Other	Open -	6/13/2005; Last		3 5125 5.15	214 - Unspecified Solvent Mixture	1	
	Alcoa Global Fasteners (aka Kaynar MFG						Industrial	Lubricating Oil			RWQCB			Agency / Tiered	Remediation	inspection on			343 - Unspecified Organic Liquid Mixture 352 - Other Organic Solids	-	
130	Division)	800 S. State College Blvd.	Fullerton	92831	4565 - ESE	10.47 acres	Cleanup	Used Oil	33.8647	-117.88947	OCHCA	12/16/2010	None	Permit	as of 5/6/2009	1 '	CAD008289183		611 - Contaminated Soils from Site Clean-up	11/30/2010	14
																		î .	343 - Unspecified Organic Liquid Mixture		
																Last	CAR000175257		352 - Other Organic Solids	[
İ	Carolina Supply Chain Services (aka Reckitt															inspection on	CAC002585079	00.330	Blank/Unknown	⊣	
131	Benckiser, Inc.; aka Albertson's, Inc.)	701 S. Sally Pl.	Fullerton	92831	932 - SE	8.15 acres	OCHCA HWSTS	Unknown	33.8659	-117.90225	оснса	12/16/2010	None	None	Nothing found	1 '	CAP000067801		<u> </u>	12/1/2010	13
																	CAC000110677				
					İ													394.792 8 9655	Blank/Unknown		
																			211 - Halogenated Solvents 214 - Unspecified Solvent Mixture		
																Ì			343 - Unspecified Organic Liquid Mixture		
																			351 - Organic Solids with Halogens		
	•							Volatile Organic					ļ		Camaniakad				352 - Other Organic Solids		
	S C I F Fullerton, LLC (aka Weber Aircraft; aka						OCHCA Industrial	_						Tiered	Completed - Case Closed as	Closed as of	CAD009608894		611 - Contaminated Soils from Site Clean-Up 741 - Liquid with Halogen Organic		
132	Monogram Systems; aka Weyerhaeser Company)	1300 E. Valencia Dr.	Fullerton	92831	597 - SSE		Cleanup	TCE	33.86678	-117.90531	RWQCB	12/16/2010		Permit	of 12/2/2003		CAC002613721		Blank/Unknown	11/2/2010	20
122	Santa Fe Pacific Realty Corporation	1300 1330 F Valencia De	C	02024	F44 565		DT00 111.00									Nothing					
133	Santa Fe Pacific Realty Corporation	1300-1330 E. Valencia Dr.	Fullerton	92831	544 - SSE	> 0.5 acres	DTSC - HWTS	Unknown	33.866/4	-117.90496	None	9/13/2010	None	None	Nothing found	Found Nothing	CAD000314617	Nothing Found	Nothing Found	11/2/2010	10
134	Flemming Environmental	1372 E. Valencia Dr.	Fullerton	92831	447 - SSE	> 0.5 acres	DTSC - HWTS	Unknown	33.86679	-117.90422	None	9/13/2010	None	None	Nothing found	_	CAC002651910	Nothing Found	Nothing Found	11/2/2010	10
	Wells Fargo Bank (aka Hoyt Tool, Inc.; aka Coit															Nothing		_	Blank/Unknown	12,1,2020	
135	Tool, Inc.)	1388 E. Valencia Dr.	Fullerton	92831	441 - SSE	> 0.5 acres	DTSC - HWTS	Unknown	33.86679	-117.90398	None	9/13/2010	None	None	Nothing found		CAC002657528			11/2/2010	12
136	Acutek U.S. Inc.	1488 E. Valencia Dr.	Fullerton	92831	649 - SSE	> 0.5 acres	DTSC - HWTS	Unknown	33.8668	-117.90242	None	9/13/2010	None	None	Nothing found	Nothing Found	CAL000346370	Nothing Found	Nothing Found	11/2/2010	10
												2,20,2020		110.110	Troums round	Nothing	CAEGO0340370	Actual Location	Nothing Found	11/2/2010	10
137	Batesville Casket Co.	1500 E. Valencia Dr.	Fullerton	92831	683 - SSE	6.20 acres	DTSC - HWTS	Unknown	33.8668	-117.90227	None	9/13/2010	None	None	Nothing found		CAL000160756	2.2316	Blank/Unknown	11/2/2010	14
138	Dole Fresh Fruit Corporation (aka AEW)	1510 E. Valencia Dr.	Fullerton	92831	716 - SSE	~ 2 acres	DTSC - HWTS	Unknown	33.8668	-117.90213	None	0/13/2010	Nama	Naua	M-4L: £ J	Nothing	64 6004 4 40 6 60		AL INC.		
1	tare on boundon (and AL va)	The second secon	. anci con	22031	, 10 JJL	2 45.03	D.30 119713	OTHER PROPERTY.	33.0000	117.50213	None	9/13/2010	None	None	Nothing found	Last	CAC001140568	Nothing Found	иошия гоила	11/2/2010	11
	Vegi-Land Sales (aka J&J Mobile Service; aka Dole															inspection on	CAC002275057				
139	Fresh Fruit; aka Veg-Land)	1518 E. Valencia Dr.	Fullerton	92831	740 - SSE	~ 2 acres	DTSC - HWTS	Unknown	33.8668	-117.90203	OCHCA	12/16/2010	None	None	Nothing found		CAL000222981	Nothing Found		11/2/2010	11
																Last			343 - Unspecified Organic Liquid Mixture 352 - Other Organic Solids		
															1	inspection on	l		352 - Other Organic Solids 741 - Liquid with Halogenated Organic Compound		
140	National Technical Systems, Inc.	1536 E. Valencia Dr.	Fullerton	92831	803 - SSE	4.13 acres	OCHCA HWSTS	Unknown	33.8668	-117.90178	OCHCA	12/16/2010	None	None	Nothing found	,	CAD982013625	66.2934	Blank/Unknown	11/2/2010	18
								Granlina Other			Ī	٦	1 7				l		211 - Halogenated Solvents		
					1	ļ	I	Gasoline, Other Chlorinated							Completed -		l		214 - Unspecified Solvent Mixture 352 - Other Organic Solids		
								Hydrocarbons		ĺ		j			Case Closed as		CAD981390909		352 - Other Organic Solids Blank/Unknown		
	Graphics Tech, LLC (aka Graphic Techonology;						OCHCA	PCE TCE,						ļ	of 10/30/2003	9/13/1991; No	CAL000170819		343 - Unspecified Organic Liquid Mixture]	
141	aka American Electronics, Inc.; aka Graphics	1600 E. Valencia Dr.	Fullerton	02021	1020 555		HWSTS/Industria		32 86501		OCHCA	12/16/2010	Nama				CAL000172479			1	
141	Luvuj	1000 L. Valelillä DI.	unerton	3∠031	1030 - 636	J.OJ acres	l Cleanup	SOIVERIS, VUC	- 18dda.cc	117.90092	KAAACR	12/16/2010	None	None		as of 4/28/10 Nothing	CAX000044560			11/2/2010	20
142	Viele & Sons, Inc.	1820 E. Valencia Dr.	Fullerton	92831	1908 - E	1.61 acres	DTSC - HWTS	Unknown	33.86684	117.89786	None	9/13/2010	None	None	Nothing found	-	CAL000285918	Nothing Found	Nothing Found	11/2/2010	10
																100			*		
	Cor-O-Van Moving & Storage (aka Cor-O-Van Warehousing & Distribution; aka Norelco, Inc ;															Mathins	CAC002639308	, ,	aca object to the	4	
		2100 E. Valencia Dr.	Fullerton	92831	3196 - E	2.41 acres	DTSC - HWTS	Unknown	33.86687	117.89354	None	9/13/2010	None !	None	Nothing found		CAL000297842 CAL000148170		352 - Other Organic Solids 352 - Other Organic Solids	11/2/2010	12
					***************************************							,,				Nothing			Control Organic Johns	11/2/2010	
144	Kent H. Landsberg	2100 E. Valencia Dr. Ste. B	Fullerton	92831	3196 - E	2.41 acres	DTSC - HWTS	Unknown	33.86687 -	117.89354	None	9/13/2010	None I	None	Nothing found	Found	CAC002204721	Nothing Found	Nothing Found	11/2/2010	9
145	Ofra Inc.	2100 E. Valencia Dr. Ste C	Fullerton	92921	3196 - E	2.41 acres	OTSC - HWTS	Unknown	22 00007	117.89354	None	0/12/2010	Non-	Nana T		Nothing	CACOOSES		21 141 1	14.15.11	
140	5110 0.00	2200 E. Valencia DI. Ste C	i anei toli	2203I	2130 - E	2.71 80163	213C - UAA12	OHANIOWII	33.0008/ -	11/.03334	IADILE ,	9/13/2010	None I	None i	Nothing found	Found Nothing	CAC002577914	1.0815	Blank/Unknown	11/2/2010	11
146	Apace	2100 E. Valencia Dr. Ste D	Fullerton	92831	3196 - E	2.41 acres [OTSC - HWTS	Unknown	33.86687 -	117.89354	None :	9/13/2010	None (None I	Nothing found		CAC001436256	Nothing Found	Nothing Found	11/2/2010	9
				-				· · · · · · · · · · · · · · · · · · ·													

	I							1=	1					-1							
	•				Distance			Detections of Chemicals of									1	LIA ZNIET VACA-			
Мар					(feet) -			Concern (PCE, TCE			Overseeing	İ						HAZNET Waste Types and		Drive-by	
Ref					Direction	Property Acres		perchlorate in			Regulatory	File Review	CERCLIS	Envirostor	GeoTracker	County HCA		Quantities (in		Date and	Site Screening or
No.	Site Name	Address	City	Zip	From FM8	1 ' '	Regulatory List	Groundwater)	Latitude	Longitude	Agency	Date	Status	Status	Status	Status	EPA ID#	tons)	HWTS California Waste Codes & Descriptions	info	Reassessment Priority
				1						Ť	1	<u> </u>				12.0		71.0479	Blank/Unknown		neassessment Honey
]			ļ					CAL000325313	0.345	352 - Other Organic Solids		
	Southern California Precision Machining Inc. (aka	a														Last	CAR000161802	19.7033	Blank/Unknown		
	Glenair Fullerton; aka John Kamicolaz; aka Mr							Oily Water. Waste								inspection on	CAD000305540				
147	Bares Furniture Co.)	2300 E. Valencia Dr.	Fullerton	92831	4032 - E	> 1 acres	OCHCA HWSTS	Coolant	33.86689	-117.89076	ОСНСА	12/16/2010	None	None	Nothing found	7/22/10	CAD981615230			11/2/2010	14
İ					l											Nothing					
148	G T Price Products Inc.	2320 E. Valencia Dr.	Fullerton	92831	4118 - E	> 2 acres	DTSC - HWTS	Unknown	33.8669	-117.890475	None	9/13/2010	None	None	Nothing found			Nothing Found	Nothing Found	11/2/2010	8
140	Gosiger West (aka Gosiger, Inc.)	2334 E. Valencia Dr.	rta	02024	4165 - E	> 1 acres	DTSC - HWTS	Unknown	22.05550	147,00022	 	0 42 5040	I.			Nothing	CAL000330736				
145	Goorger West (and Goorger, Inc.)	2334 C. Valencia Di.	ratieiton	32031	4103 - E	> 1 acres	DISC - HWIS	CHKHOWH	33,00053	-117.89032	None	9/13/2010	None	None	Nothing found	rouna	CAC002628039 CAL000289119	5.6295	Blank/Unknown	11/2/2010	10
																İ	CAL000289119				
	FBI Express. Inc. (aka U.S. Delivery; aka Todd											İ				Nothing	CAL000333778	5 27505	Blank/Unknown	_	
150	Pollock; aka American Fleet Service)	1250 E. Walnut Ave.	Fullerton	92831	701 - W	1.62 acres	DTSC - HWTS	Unknown	33.86833	-117.90628	None	9/13/2010	None	None	Nothing found	1 ~		6.32172	Blank/Unknown	11/2/2010	15
	,										_									11/2/2010	15
-				ĺ							ì				Completed -					 	
	All-Roads Moving and Storage (aka J&B Industria	al													Case Closed as	Nothing					
151	Property Fund LP)	1400 E. Walnut Ave.	Fullerton	92831	165 - E	~ 1.5 acres	GeoTracker LUST	Gasoline Gasoline	33.86831	-117.904392	RWQC8	9/20/2010	None	None	of 10/1/1991	Found	CAC001200136	Nothing Found	Nothing Found	11/2/2010	11
1.			l													Nothing					
152	Realty Associates Fund	1404 E. Walnut Ave.	Fullerton	92831	150 - E	0.16 acres	DTSC - HWTS	Unknown	33.86836	-117.90424	None	9/13/2010	None	None	Nothing found			Nothing Found	Nothing Found	11/2/2010	9
	Canning Gumm Inc. Western Division (aka						l							Ì		Nothing	CAP000043307				
153	Macdermid, Inc.)	1404 E. Walnut Ave. Ste. B	Fullerton	92831	150 - E	0.16 acres	DTSC - HWTS	Unknown	33.86836	-117.90424	None	9/13/2010	None	None	Nothing found	Found	CAR000059758	Nothing Found	Nothing Found	11/2/2010	9
															Completed -						
ł	Inland Computer Products (aka Beckman			1 .			OCHCA Industrial				OCHCA				Case Closed as	Closed as of					
,	Instruments; aka Allergan)	1410 E. Walnut Ave.	Fullerton	92831	136 - F	~ 1.5 acres	Cleanup	VOC, Low PCE	33 86836	-117.90411	RWQCB	12/16/2010	None .	None	of 2/14/1990		CAX000073437	Nothing Found	Nothing Sound	11/2/2010	15
	, , , , , , , , , , , , , , , , , , , ,				 			100, 1011 / 12	55.55555	227120122	111145	12/10/2010	Ittoria	Hone	012,21,2330	Nothing	C-1/(0000/343/	Wouling Found	restring round	11/2/2010	13
155	The Trident Company	1430 E. Walnut Ave.	Fullerton	92831	183 - E	~ 2 acres	DTSC - HWTS	Unknown	33.86836	-117.90358	None	9/13/2010	None	None	Nothing found	_	CAL930973428	Nothing Found	Nothing Found	11/2/2010	11
	Momentum Textiles (aka I&B Industrial											, , , , ,			1	Nothing				11,2,2010	
156	Properties Fund One)	1450 E. Walnut Ave.	Fullerton	92831	165 - E	~ 4 acres	DTSC - HWTS	Unknown	33.86831	-117.904392	None	9/13/2010	None	None	Nothing found	Found	CAC001075832	0.187	343 - Unspecified Organic Liquid Mixture	11/2/2010	11
																	CAC002647481			1	
																İ	CAD981680952				į
				Ì				i									CAC002629577				
								Oil Oil Filters, Oily									CAL000068082				
								absorbent Ink.									CAX000087312				
	Kraft Foods, Inc. (aka Kraft Foods; aka Claussen							Lead Floroscent			l					Last		0 1749	342 - Organic Liquids with Metals		
157	Pickle Co.; aka Nalco Chemical; aka Fullerton Foods)	1500 E. Walnut Ave.	Fullerton	00001	704 5	F 47		Tubes, Acid	22.05027	447.00470		40 46 60040	l	<u> </u>		inspection on			352 - Other Organic Solids	1 1	
13/	roods)	1500 E. Walhut Ave.	Fullerton	92831	704 - E	5.17 acres	OCHCA HWSTS	Batteries	33.86837	-117.90172	IOCHCA	12/16/2010	None	None	Nothing found		CAL000050746	291.756	Blank/Unknown	11/2/2010	13
				1												Last	CALBOORS 2518				
158	Mihm's Truck Repair (aka B&B Truck Services)	1526 E. Walnut Ave.	Fullerton	92831	956 - F	~ 1.5 acres	OCHCA HWSTS	Coolant Waste Oil	33 86838	_117 00099	OCHCA	12/16/2010	None	None	Nothing found	inspection on	CAL000263610	Nothing Found	Nothing Found	11/2/2010	41
130	mining mach repair falla bab mach services	2320 E. Wallati (Te.	Tunciton	32031	330 -	2.5 deres	OCHEA INVOIS	Coolaire Waste Oil	35.00050	117.70000	OCITCA	12/10/2010	None	None	Nothing loutin	Nothing	CAE000223121	Nothing Found	Nothing Found	11/2/2010	11
159	Westline	1548 E. Walnut Ave.	Fullerton	92831	1276 - E	~ 1.5 acres	DTSC - HWTS	Unknown	33.86851	-117.899835	None	9/13/2010	None	None	Nothing found		CAD000321448	Nothing Found	Nothing Found	11/2/2010	11
																Nothing	0.0000000000000000000000000000000000000	risaning round	Trouble Touris	11/2/2010	
160	Good Water Warehouse (aka Whitnon/GMN)	1700 E. Walnut Ave.	Fullerton	92831	1778 - E	~ 2 acres	DTSC - HWTS	Unknown	33.86863	-117.89819	None	9/13/2010	None	None	Nothing found	Found	CAL000100119	Nothing Found	Nothing Found	11/2/2010	8
[lww Incorporated (aka Westport Graphics Inc ;			Ţ												Nothing	CAC000923304		343 - Unspecified Organic Liquid Mixture	7,1	
	aka Mysee Designery)	1718 E. Walnut Ave.	Fullerton	92831	1817 - E	~ 2 acres	DTSC - HWTS	Unknown	33.86863	-117.89805	None	9/13/2010	None	None	Nothing found	Found	CAL000082089			11/2/2010	8
ì	Riccar America & Vac Pros (aka Acacia Business		-													Nothing					
162	Center)	1800 E. Walnut Ave.	Fullerton	92831	2016 - E	3.72 acres	DTSC - HWTS	Unknown	33.86864	-117.89739	None	9/13/2010	None	None	Nothing found		CAL000221238	0.108	214 - Unspecified Solvent Mixture	11/2/2010	8
											l			. :		Nothing					
163	Bob Evans Farms Corporation	1820 E. Walnut Ave.	Fullerton	92831	2068 - E	~ 2 acres	DTSC - HWTS	Unknown	33.86864	-117.89722	None	9/13/2010	None	None	Nothing found	Found		Nothing Found	Nothing Found	11/2/2010	8
	Sun Pacific Inc. (aka Texture Glass Industries															N1=+b!	CAC001469520				
	Sun Pacific Inc. (axa Texture Glass Industries)	2030 E. Walnut Ave.	Eußarten.	02021	2578 - E	1 10 2000	DTSC - HWTS	Unknown	22 96065	-117.89553	None	0/12/2010	None	None			CAC002647879	0.561	242		_
104	corporation, and resture diass industries)	LUDU L. WERRILL MYE.	rullerton	32031	22/0-E	1.10 acres	D19C - UAA12	Unknown Waste Oil	JJ.00865	-11/.83353	Molle	9/13/2010	ivone	None	Nothing found		CAC002584136	u.501	343 - Unspecified Organic Liquid Mixture	11/2/2010	9
					:			Refrigeration							1	Last inspection on	CAL000346138				
165	Anderson Air Conditioning LP	2100 E. Walnut Ave.	Fullerton	92831	2744 - E	~ 0.5 acres	OCHCA HWSTS	-	33.86865	-117.89498	OCHCA	12/16/2010	None	None	Nothing found			Nothing Found	Nothing Found	11/2/2010	ا ء
1			- I amorton	102002		0.5 46.65	G C T C T T T T T T T T T T T T T T T T	ridate on	55.0005	117.05430	Johnson	12, 10, 2010	Itolic	ITOTIC	Nothing round	3/3/10	CAL000023014	Nothing round	Notining Found	11/2/2010	
				1													CAL000346263				
	Tri Pacific Heating & Air Conditioning (aka Span C)												-		Nothing		0 561	343 - Unspecified Organic Liquid Mixture	┥ !	
166	Matic, Inc.; aka Quality Industrial Systems)	2116 E. Wainut Ave.	Fullerton	92831	2834 - E	0.46 acres	DTSC - HWTS	Unknown	33.86865	-117.89468	None	9/13/2010	None	None	Nothing found	_			352 - Other Organic Solids	11/2/2010	7
								Universal waste					[]			Last			214 - Unspecified Solvent Mixture	1	
	Nordstrom. Inc #391 (aka Nordstrom Design							Paint								inspection on			352 - Other Organic Solids		l
	Center)	2200 E. Walnut Ave.	Fullerton	92831	3291 - E	~ 2 acres	OCHCA HWSTS	Thinner/Filters	33.86866	-117.89317	OCHCA	12/16/2010	None	None	Nothing found		CAL000064266	18.6317	Blank/Unknown	11/2/2010	7
	Fullfillment Corporation of America (aka		<u>_</u>						Ţ]	Nothing					
168	Insulated Shipping Container)	2340 E. Walnut Ave.	Fullerton	92831	4065 - E	2.57 acres	DTSC - HWTS	Unknown	33,86868	-117.89061	None	9/13/2010	None	None	Nothing found	~~~	CAC000505912		Nothing Found	11/2/2010	6
	In a Francisco A. V.	2254 5 34-1-1-1		000		[_		,			<u> </u>		[<u> </u>	Nothing			741 - Liquid with Halogen Organic Compound		
169	Jaco Environmental, Inc.	2354 E. Walnut Ave.	Fullerton	92831	4144 - E	1 acres	DTSC - HWTS	Unknown	33.86868	-117.89035	None	9/13/2010	None	None	Nothing found				Blank/Unknown	11/2/2010	8
170	Smallov 2 Co	2250 C Wolant &	Fullerin	02024	4105 5		DTEC INCTE			11700000	 	. /22 /22 2	l İ	j <u>.</u>	1 3	Nothing	~~~		Blank/Unknown		
1/0	Smalley & Co.	2358 E. Walnut Ave.	Fullerton	92831	4165 - E	~ 1.5 acres	DTSC - HWTS	Unknown	33.86868	-117.89028	None	9/13/2010	None	None	Nothing found		CAC002630490	1.89	Blank/Unknown	11/2/2010	88
171	H&H Distrubution	Valencia Dr & Acacia Ave	EuBorton	02921	1794 5	> 0.25 acres	DTSC - HWTS	Unknown	22 05502	117 00007	Mono	0/12/2010	None	l l	I	Nothing	CA CO0120C00.	2.0	Diagle (Up by some	44/2/2222	
		resented of a Acadia Ave	promerton	22031	±/24°C	رح U.حا عدا ا	DI3C - U4A13	CHARIOWII	C0000.LL	-117.89807	MOHE	9/13/2010	INOUG	None	Nothing found	rouna	CAC002386094	J.0	Blank/Unknown	11/2/2010	11

Map Ref	Site Name	Address	City	Zìp	1	Property Acres (length x width)	Regulatory List	Detections of Chemicals of Concern (PCE, TC perchlorate in Groundwater)		Longitude	1 7	1	1	Envirostor Status		County HCA	EPA ID#	HAZNET Waste Types and Quantities (in tons)	HWTS California Waste Codes & Descriptions	Drive-by Date and Info	Site Screening or Reassessment Priori
	SLIC - Regional Water Quality Control Board			1		†		,				1			T T T T T T T T T T T T T T T T T T T	Julias	ETT (ID)	tonsy	134 15 California Waste Codes & Bescriptions	isilo	Reassessment Phon
	Spills Leaks Investigations, and Cleanups								İ			-									
	REF - Department of Toxic Substances Control											l									
	Site refered to another agency						1				•										·
	LUST - Leaking Underground Storage Tank									İ	1.		Ì								
	CERCLIS - Comprehensive Environmental															1				l	
	Response, Compensation, and Liability Act								1												
	CERCLIS -NFRAP - CERCLIS archived sites					ĺ							l								
	AWP - Department of Toxic Substances Control																				
	Annual Work Plan Site REF -						1						İ			1					
	DTSC sites referred to other agencies		1								1										
	OCHCA - Orange County Health Care Agency																				
	Industrial Site Cleanup List					ļ												1			
	HAZNET - large volume hazardous waste shipper																				
	OCWD - Site identified by Orange County Water											Ì]								
	District	TCE - trichloroethylene		-	-																
-	Table 1 Project Data Sheet				-					ļ					-						

Table 2

Project Priority Chart (Source: DTSC)

Map Ref No.	Site Name	Address	City	Zip	Site Distance	Site Known to Have Used Solvents on Regular Basis/In- Large Volume	Site Lies Within Footprint of Localized Plume	Site Currently Under Regulatory Oversight	Number of Years in Operation	PCE/TCE Confirmation	Property Size	Site with Large Volumes of Blank/Unknown Disposed	TOTAL	Site in CERCLIS
													,	
	Priority Chart Grading System				_									
No.	Criteria	Points Assigned												
		0.00 - 0.25 mile = +3												
		0 25 - 0 50 mile = +2											-	
		0 50 - 0 75 mile = +1												
1	Site Distance from FM-8 well	0.75 - 1.00 mile = +0												
		Yes = +3									i			
2	Is the site known to have used solvent on a regular basis?	No = +0												
		Yes = +2			-							*****		
3	Does the site lie within the footprint of a localized plume?	No = +0												
		Yes = +0												
4	Is the site currently under a regulatory order for investigative or remedial action?	No = +3												
		21 years or more = +3												
		11 - 20 years = +2	İ							ļ				
5	Number of years site has been in operation at this location	0 - 10 years = +1		İ					}					
		Yes = +2					·							
6	Use of halogenated organic compounds listed in DTSC's HWTS Database	No = +0												
		Large (> 1 acre) = +2												
1		Medium (0,25 - 1 0 acre) = +1												
7	Size of the site/property	Small (< 0.25 acre) = 0										·		
		Yes = +2												
8	Has the site dispose of large volumes of blank/unknown HAZNET Wastes (≥ 1 ton)?	No = +0									•		-	

Map Ref					ł .	Have Used Solvents on Regular Basis/In-	Site Lies Within Footprint of Localized	Site Currently Under Regulatory	Number of Years in	PCE/TCE	Property	Site with Large Volumes of Blank/Unknown		Site in
	Site Name	Address	City	Zip	from FM8	Large Volume	Plume	Oversight	Operation	Confirmation	Size	Disposed	TOTAL	CERCLIS
	S C I F Fullerton, LLC. (aka Weber Aircraft; aka Monogram Systems; aka Weyerhaeser	1200 F Valoraia Ba	- ,, ,	2222						_				
132	Company) Graphics Tech, LLC. (aka Graphic Techonology; aka American Electronics, Inc.; aka	1300 E. Valencia Dr.	Fullerton	92831	3	3	2	3	3	2	2	2	20	No
1.41	Graphics 1900)	1600 F. Voloncia Dr	F. II auton	02024	_	_				_		_		
141 140	National Technical Systems, Inc.	1600 E. Valencia Dr.	Fullerton		3	3	2	3	3	2	2	2 .	20	No
		1536 E. Valencia Dr.		92831	3	3	2	3	3	0	2	2	18	No
35 66	Orange County Metal Processing Terra Universal, Inc. (aka California Shirt Sales)	1711 E. Kimberly Ave.		92831	2	3	2	3	3	0	2	2	17	No
69		800 S. Raymond Ave		92831	2	3	2	3	3	0	2	2	17	No
69	Orange County Paint	1710 E. Rosslynn Ave.	Fullerton	92831	2	3	2	3	3	0	2	2	17	No
-	Omni Optical (aka Omni Optical Products, Inc.; aka Coca Cola Foods; aka Nutri-Foods International, Inc.)	2505	- II .			_		_						
5	BC2 Environmental Rental (aka Avory Streech; aka Atlas Copco, Inc.; aka Prime Energy	360 S. Acacia Ave.	Fullerton	92831	2	3	2	3	2	2	2	0	16	No
l I		1212 5 4-1-4		00004			_	_	_	_]]
19	Systems)	1212 E. Ash Ave.		92631	3	3	2	3	3	0	0	2	16	No
20		1217 E. Ash Ave.	Fullerton	92831	3	3	-2	3	3	0	0	2	16	No
33	Ruan Transportation Corporation (aka Johnson Controls Battery Group, Inc.; aka Ruen	4550 5 Kimb 1 a	J	02021		_		_						
33		1550 E. Kimberly Ave.	Fullerton	92831	2	3	2	0	3	2	2	2	16	Yes
	Tops Auto Body (aka K&N Automotive; aka Trinity Auto Collision Inc ; aka Honda Car	500 5			_	_	_	_						
44	Specialty) Mesa Cold Storage, Ltd (aka Frozsun Food; aka New West Foods, aka AmeriCold	500 S. Raymond Ave. Unit C	Fullerton	92831	3	3	2	3	3	0	2	0	16	No
63		700 C Daynes and Ave			_	_	_	_	_	_	_			
62 70		700 S. Raymond Ave.		92831	2	3	2	3	2	0	2	2	16	No
70		1726 E. Rosslynn Ave.	Fullerton	92831	2	3	2	0	3	2	2	2	16	No
72	St. Hart Container Corporation, Division of Subclipse (aka St. Hart Container	1001 F. Barata and A.	- "	00004			_		_	_				
-		1901 E. Rosslynn Ave.		92831	. 1	3	2	3	3	0	2	2	16	No
73		1911 E. Rosslynn Ave.		92831	1	3	2	3	3	0	2	2	16	No
14		650 S. Acacia Ave.		92831	2	3	2	3	1	0	2	2	15	No
39		350 S. Raymond Ave.		92831	3	3	2	0	3.	2	2	0	15	No
42		500 S. Raymond Ave.		92831	3	3	2	3	2	0	0	2	15	No
		711 S. Raymond Ave. Unit B	Fullerton	92831	2	3	2	3	2	0	1	2	15	No
	YRC Enterprise Services DBA USF Reddaway (aka EDO Corp, Western Div ; aka		i											1
_		300 S. State College Blvd.	Fullerton		0	3	0	3	3	2	2	2	15	No
/5	Kairak aka Don Green's Sales Inc.	500 S. State College Blvd.	Fullerton	92831	0	3	2	3	3	0	2	2	1 5	No
			l											
	FBI Express, Inc. (aka U.S. Delivery; aka Todd Pollock; aka American Fleet Service)	1250 E. Walnut Ave.	Fullerton	92831	3	0	2	3	3	0	2	2	15	No
	Kraft Foods, Inc. (aka Kraft Foods; aka Claussen Pickle Co.; aka Nalco Chemical; aka		l								İ			
	Fullerton Foods)	1500 E. Walnut Ave.		92831	3	0	2	3	3	0	2	2	15	No
		1410 E. Walnut Ave.		92831	3	0	2	3	3	2	2	0	15	No
13	Yokohama Tire Corporation	601 S. Acacia Ave.	Fullerton	92831	2	3	2	3	2	0 1	2	0	14	No
1	Plasticolor Molded Products Inc. (aka Plasticolor Molded Products; aka Lokalex Inc.;		_ ,,		_									, .
16	aka Specialty Extrusion Corporation; aka Specialty Extrusion Ltd.)	801 S. Acacia Ave.	Fullerton	92831	2	0	2	3	3	0	2	2	14	No
			<u>.</u>							ĺ				
25	Unitdesigned, Inc. (aka Euro West Inc.; aka Etl Garage; aka Programmed Composites)			92831	3	0	2	3	3	2	1	0 .	14	No
		331 S. Hale Ave.		92831	1	3	2	3	1	0	2	2	14	No
		331 S. Hale Ave. Ste A&B		92831	1	3	2	3	1	0 -	2	2	14	No
		2500 E. Kimberly Ave.		92831	0	3	2	3	2	0	2	2	14	No
		529 S. Raymond Ave.		92831	3	3	2	3	2	0	1	0	14	No
		655 S. State College Blvd. #27		92831	0	3	2	3	2	0	2	2	14	No
-		800 S. State College Blvd.		92831	0	3	2	0	3	2	2	2	14	No
·		1500 E. Valencia Dr.	Fullerton	92831	3	0	2	3	2	0	. 2	2	14	No
	Southern California Precision Machining Inc. (aka Glenair Fullerton; aka John						ļ							
		2300 E. Valencia Dr.		92831	0	3	2	3	3	0	11	2	14	No
		1818 E. Rosslynn Ave.		92831	2	0	2	0	3	2	2	2	13	No
		501 S. Acacia Ave.	Fullerton		2	0	2	3	2	0	2	2	13	No
17	Undercar Parts Corporation (aka Accent Plastics, Inc.)	1206 E. Ash Ave.	Fullerton	92831	3	0	2	3	3	0	0	2	13	No
										<u></u>				

			_		T				T					
						Site Known to	Site Lies							
								611 6 11				<u> </u>		
Man				l	C'.	Have Used	Within	Site Currently				Site with Large		
Map Ref					Site	Solvents on	Footprint of	Under	Number of			Volumes of		
	Sita Nama	a delice of	.		Distance	Regular Basis/In-	Localized	Regulatory	Years in	PCE/TCE	Property	Blank/Unknown		Site in
No.	Site Name	Address	City			Large Volume	Plume		Operation	Confirmation	Size	Disposed	TOTAL	CERCLIS
18	Raymac Grinding Co.	1207 E. Ash Ave.	Fullerton	92831	3	0	2	3	3	00	0	2	13	No
l I.,									İ					
	5 Star Auto Care (aka Don's Auto Body; aka Specialized Machine & Metallizin)	500 S. Raymond Ave. Ste H		92831	3	3	2	3	2	0	0	0	13	No
54	Semaan Printing Co, Inc.	535 S. Raymond Ave.	Fullerton	92831	3	. 3	2	3	1	0	1	0	13	No
56	Bavarian Autotech's (aka Bavarian Auto Tech)	551 S. Raymond Ave.	Fullerton	92831	3	0	2	3	3	0	0	2	13	No
89	Southern California Precision (aka Fullerton Industrial Park)	641 S. State College Blvd.	Fullerton	92831	0	3	2	3	11	0	2	2	13	No
131	Carolina Supply Chain Services (aka Alberton's, Inc.; aka Reckitt Benckiser, Inc.)	701 S. Sally Pl.		92831	3	0	2	3	1	0	2	2	13	No
8	Right Connection Sportswear Company (aka Red Hat Society)	371 S. Acacia Ave.		92831	2	3	2	3	1	0	1	0	12	No
29	Southern California Edison (aka California Almond Growers)	325 S. Hale Ave.		92831	2	0	0	3	3	: 0	2	2	12	No
46	Beto's Paint & Body Inc.	500 S. Raymond Ave. Ste F	Fullerton	92831	3	3	2	3	1	0	0	0	12	No
55	Faber Laboratories	539 S. Raymond Ave.	Fullerton	92831	. 3	0	2	3	. 3	0	1	0	12	No
65	Roys Transmission Service	715 S. Raymond Ave.	Fullerton	92831	2	0	2	3	3	0	0	2	12	No
8.7	MOPC Printing (aka Christian Printing Service)	579 S. State College Blvd.	Fullerton	92831	0	3	2	3	3	0	1	0	12	No
90	Future Tattoo & Body Piercing (aka Perfect Coat, Inc.; aka Pink Tiger)	645 S. State College Blvd.		92831	0	3	2	3	3	0	1	0	12	No
	Wells Fargo Bank (aka Hoyt Tool, Inc.; aka Coit Tool, Inc.)	1388 E. Valencia Dr.	Fullerton	92831	3	0	2	3	11	0	1	2	12	No
	Cor-O-Van Moving & Storage (aka Cor-O-Van Warehousing & Distribution; aka		l										:	
	Norelco, Inc.; aka Foxx Building Services, Inc.)	2100 E. Valencia Dr.	1	92831	1	0	2	3	2	0	2	2	12	No
	Bimbo Bakeries USA (aka Airborne Express)	366 S. Acacia Ave.		92831	2	0	2	3 .	2	0	2	0	11	No
11	Khyber Foods Incorporated (aka Alnor Oil)	500 S. Acacia Ave.	Fullerton	92831	2	0	2	3	1	0	1	2	11	No
22														, 1
22	Performance Dip Braze (aka Santana Services; aka Western Roto Engravers, Inc.)	1224 E. Ash Ave.	Fullerton	92831	3	0	2	3	3	0	0	0	11	Yes
22	County Charles 1 1 1 0 1 Bi OM Control		<u> </u>		_	_								1
	Security Signal Devices Inc. (aka Crenshaw Die & Manufacturing Corporation)	1227 E. Ash Ave.		92831	3	0	2	3	3	0	0	0	11	No
	JB Hunt	2001 E. Kimberly Ave.	-	92831	2	0	2	3	1	0	1	2	11	No
	Terry's Automotive, Inc. (aka Auto Hospital)	500 S. Raymond Ave. Unit D	Fullerton	92831	3	0	2	3	1	2	0	0	11	No
	Topline Auto Collision LLC (aka Wheels Auto Body & Paint Shop; aka Topline Paint &	500 C Parameter 4 A 18 77			_		_	_		_				1
-	Body Inc.; aka Leonardo's Paint & Body Shop)	500 S. Raymond Ave. #I	Fullerton		3	0	2	3	3	0	0	0	11	No
	Larsco Corp. (aka Labeltech)	503 S. Raymond Ave.	Fullerton			0	2	3	2	0	1	0	11	No
	Acme Door Closers CCJ Corporation	600 S. Raymond Ave.		92831	3	0	2	. 3	3	0	0	0	11	No
	·	602 S. Raymond Ave.		92831	3	0	2	3	1	0	2	0	11	No
59	Lone Star Termite and Pest Control Inc.	606 S. Raymond Ave.		92831	3	0	2	3	1	0	2	0	11	No
91	Native Gear	651 S. State College Blvd.	Fullerton	92831	0	3	2	3	2	0	1	0	11	No
93	Classic Silk Screen Design	CEA C Chata Callega Blad Hair 45	F. 11	02024				_	_	_	_	_		
	Dole Fresh Fruit Corporation (aka AEW)	651 S. State College Blvd. Unit 15		92831	0	3	2	3	1	0	2	0	11	No
130	Dole Fresh Fruit Corporation (aka AEW)	1510 E. Valencia Dr.	Fullerton	92831	3	0	2	3	1	0	2	0	11	No
120	Vegi-Land Sales (aka J&J Mobile Service; aka Dole Fresh Fruit; aka Veg-Land)	1518 E. Valencia Dr.	F. II and an	92831	2		2		.					
	Ofra Inc.	2100 E. Valencia Dr. Ste C		92831	3	0	2	3	1	0	2	0		No
	All-Roads Moving and Storage (aka J&B Industrial Property Fund LP)	1400 E. Walnut Ave.		92631	1	0	2	3	1	0	2	2	11	No
	The Trident Company	1430 E. Walnut Ave.		92831	3	0	2	3	. 1		2	0	11	No
	Momentum Textiles (aka J&B Industrial Properties Fund One)						2	3	1	0	2	0	11	No
	Mihm's Truck Repair (aka B&B Truck Services)	1450 E. Walnut Ave. 1526 E. Walnut Ave.		92831	3	0	2	3	1	0	2	0	11	No
	Winnin s Truck Repair (aka B&B Truck Services) Westline		Fullerton	92831	3	0	2	3	1	0	2	0	11	No
	H&H Distrubution	1548 E. Walnut Ave.		92631	3	0	2	3	1	0	2	0	11	No
J	City of Fullerton - Fire Department #3	Valencia Dr. & Acacia Ave.		92831	2	0	2	3	1	0	1	2	11	No
	Telatemp Corporation	700 S. Acacia Ave.		92831	2	0	2	3	1	0	2	0	10	No
	- 100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	351 S. Raymond Ave.		92831	3	0	2	3	1	0	1	0	10	No
	Inglewood Transmission Service Inc. (aka Turret La The Specialist; aka California	371 S. Raymond Ave.	Fullerton	92831	3	0	2	3	1	0	1	0	10	No No
	Autobody & Paint; aka Tury'z Concepts Inc.)	EOO S Baymand Ava Stall	Cullanta:	02024	ا ر	_	_		_			_		
	OCB Reprographics (aka Fullerton Blueprint Co., Inc.)	500 S. Raymond Ave. Ste J	Fullerton		3	0	2	3	2	0	0	0	10	No
	Spacer Connection Inc.	528 S. Raymond Ave. 711 S. Raymond Ave. Ste A		92831 92831	3	0	2	3	1	0	1	0	10	No
		900 S. Raymond Ave.	Fullerton Fullerton		2 2	0	2	3 3	2	0	1	0	10	No
ا ا	and and and actives	200 S. Raymona Ave.	i unerton	72031		V	۷	3	Τ	0	2	0	10	No

						Site Known to Have Used	Site Lies Within	Site Currently				Site with Large		
Map					Site	Solvents on	Footprint of	Under	Number of			Volumes of		
Ref	Sita Nama	Address	C:t-	7:	Distance	Regular Basis/In-	Localized	Regulatory	Years in	PCE/TCE	Property	Blank/Unknown		Site in
No. 68	Site Name Rayne Water Conditioning (aka Pacific Industrial Water System)	Address 1702 E. Rosslynn Ave.	City Fullerton	Zip 92831	-		Plume	Oversight	Operation	Confirmation	Size	Disposed	TOTAL	CERCLIS
	Juniors Professionals Ironwork (aka Remtech Restoration Corporation)	597 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	2	0	10	No
	A D S Gold, Inc.	717-J S. State College Blvd.		92831	0	0	2	3	2	0	1 1	2	10	No
	Santa Fe Pacific Realty Corporation	1300-1330 E. Valencia Dr.		92831	3	0	2	3	1	0	1	0	10	No No
134	Flemming Environmental	1372 E. Valencia Dr.		92831	3	0	2	3	1	0	1	0	10	No
	Acutek U.S. Inc.	1488 E. Valencia Dr.		92833		0	2	3	1	0	1	0	10	No
	Viele & Sons, Inc.	1820 E. Valencia Dr.	Fullerton	92831	2	0	2	3	1	0	2	0	10	No
149	Gosiger West (aka Gosiger, Inc.)	2334 E. Valencia Dr.		92831	0	0	2	3	1	0	2	2	10	No
	Siegling America	350 S. Acacia Ave.		92831	2	0	2	3	1	0	1	0	9	No
	Whitnon GMN (aka GMN Whitnon Spindell)	369 S. Acacia Ave.		92831	2	0	2	3	1	0	1	0	9	No
	S C Precision Molds, Inc.	419 S. Acacia Ave.		92831	2	0	2	3	1	0	1	0	9	No
	WD & J Machine & Engineering	443 S. Acacia Ave.		92831	2	0	2	3	1	0	1	0	9	No
21 24	Masco Sweepers, Inc. (aka Crenshaw Die and Manufacturing) Camarigg Automotive, Inc. (aka Nickolas Steel)	1223 E. Ash Ave. 1229 E. Ash Ave.		92831	3	0	2	3	1	0	0	0	9	No
26	Camarigg Automotive, inc. (aka Nickolas Steel) Southern California Trucking	1229 E. Ash Ave. 1234 E. Ash Ave. Unit D		92831 92831	3	0	2	3	1	0	0	0	9	No
27	Commonwealth Elementary School	2200 E. Commonwealth Ave.		92831	1	0	0	3	1	0	0	0	9	No
	California Almond Growers	324 S. Hale Ave.		92831	1	0	2	3	1	0	2	2	9	No
	Blue Line Foodservice Distribution	330 S. Hale Ave.		92831	1	0	2	3	1	0	2	0	9	No
	Specialty Extrusion Corporation (aka Al McDougal)	1580 E. Kimberly Ave.		92831	2	0	2	3	1 1	0		0	9	No
	Accurate Auto Performance	500 S. Raymond Ave. Ste B1		92831	3	0	2	3	1	0	0	0	9	No
	Genesis Auto Body	500 S. Raymond Ave. Ste G	Fullerton	92831	3	0	2	3	1	0	0	0	9	No No
60	United States Spring & Stamping CO, Inc.	615 S. Raymond Ave.		92831	3	0	2	3	1	0	0	0	9	No
61	Same Day Cylinder	619 S. Raymond Ave.		92831	2	0	2	3	1	0	1	0	9	No
	Ropack Corp	660 S. State College Blvd.		92831	0	0	2	3	1	0	1	2	9	No
108	College Business Park (aka Crico-HST Associates)	701 S. State College Blvd.		92831	0	0	2	3	1	0	1	2	9	No
118	Mesa Technology	733 S. State College Blvd.		92831	0	0	2	3	1	0	1	2	9	No
128	Trico Realty	765 S. State College Blvd. Unit C	Fullerton	92831	0	0	2	3	1	0	1	2	9	No
	Kent H. Landsberg	2100 E. Valencia Dr. Ste. B	Fullerton	92833	1	0	2	. 3	1	0	2	0	9	No
	Apace	2100 E. Valencia Dr. Ste D	Fullerton	92831	1	0	- 2	3	1	0	2	0	9	No
	Realty Associates Fund	1404 E. Walnut Ave.	Fullerton	92831	3	0	2	3	1	0	0	0	9	No
	Canning Gumm Inc., Western Division (aka Macdermid, Inc.)	1404 E. Walnut Ave. Ste. B	Fullerton	92831	3	0	2	3	1	0	0	0	9	No
	Sun Pacific, Inc. (aka Texture Glass Industries Corporation; aka Texture Glass										- · · ·			
	ndustries)	2030 E. Walnut Ave.	Fullerton	92831	2	0	0	3	2	0	2	0	9	No
	Acacia Career Training Facility (aka North Orange County Regional Occupational													
_	Center)	301 S. Acacia Ave.		92831	2	0	2	3	1	0	0	0	8	No
	FAAC International, Inc.	357 S. Acacia Ave.		92831	2	0	2	3	1	0	0	0	8	No
	SAAC International, Inc.	357 S. Acacia Ave. Unit 357		92831	2	0	2	3	1	0	0	0	8	No
	Fullerton INDL Park (aka A L S Corporation)	501 S. State College Blvd.		92831	0	0	2	3	1	0	2	0	8	No
\vdash	OP & F Trust & Rreef Management Rozak Engineering Inc. aka Qualitask Inc.	541 S. State College Blvd.		92831	0	0 •	2	3	1	0	2	0	8	No
	Rozak Engineering Inc. aka Qualitask Inc. Circuit Image Systems	556 S. State College Blvd. 591 S. State College Blvd.		92831	0	0	2	3 .	1	0		2	8	No
	Picture This (aka Precision Mold Base Corporation; aka OP&F Trust & Rreef	631 S. State College Blvd.		92831 92831	0	0	2	3		0	1	0	8	No
	AC Alternator & Starter Shop	651 S. State College Blvd. #17		92831	0	0	2	3	2	0	2	0	8	No
	Garner Grinding	655 S. State College Blvd. #17		92831	0	0	2	3	1	0	2	0	8	No No
	<u> </u>			J _001		· · · · · · · · · · · · · · · · · · ·	-		1	·		U	•	140
96	Superior Lift	655 S. State College Blvd. No. 31	Fullerton	92831	0	0	2	3	1	0	2	o	8	No
	Awnings by Russ (aka Trico Realty, Inc.)	689 S. State College Blvd.		92831	0	0	2	3	2	0	1	0	8	No
								. ***						
	Frico Rents (aka Javier Ornamental; aka Lympus Prints; aka Typewriter M D's)	707 S. State College Blvd.	Fullerton	92831	0	0	2	3	2	0	1	0	8	No
	American Diversifed Silver (aka Bright Polishing, Inc.)	717 S. State College Blvd.	Fullerton	92831	0	0	2	3	2	0	1	0	8	No
	G T Price Products Inc.	2320 E. Valencia Dr.	Fullerton	92831	0	0	2	3	1	0	2	0	8	No
	Good Water Warehouse (aka Whitnon/GMN)	1700 E. Walnut Ave.		92831	2	0	0	3	1	0	2	0	8	No
	ww Incorporated (aka Westport Graphics, Inc.; aka Mysee Designery)	1718 E. Walnut Ave.		92831	2	0	0	3	1	0	2	0	8	No
162	Riccar America & Vac Pros (aka Acacia Business Center)	1800 E. Walnut Ave.	Fullerton	92831	2	0	0	3	1	0	2 .	0	8	No

					· · · · · · · · · · · · · · · · · · ·	1								
		j				Site Known to	Site Lies							
			İ			Have Used	Within	Site Currently				Ch. Stall I		
Мар			ĺ		C:r-		1					Site with Large		
					Site	Solvents on	Footprint of	Under	Number of]	Volumes of		
Ref	a		i			Regular Basis/In-	Localized	Regulatory	Years in	PCE/TCE	Property	Blank/Unknown		Site in
-	Site Name	Address		Zip	from FM8	Large Volume	Plume	Oversight	Operation	Confirmation	Size	Disposed	TOTAL	CERCLIS
163	Bob Evans Farms Corporation	1820 E. Walnut Ave.	Fullerton	92831	2	0	0	3	1	0	2	0	8	No
169	Jaco Environmental, Inc.	2354 E. Walnut Ave.	Fullerton	92831	0	0	0	3	1	0	2	2	8	No
170	Smalley & Co.	2358 E. Walnut Ave.		92831	0	0	0	3	1	0	2	2	8	No
					<u> </u>		 					 	- ^	100
79	Alcoa Global Fasteners, Inc.	561 S. State College Blvd.	Fullerton	92831	0	0	2	3	1				7	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	Sprint Printing Inc.	570 S. State College Blvd.	Fullerton	92831		· · · · · · · · · · · · · · · · · · ·			1	0	1	0		No
	Accurate Industrial Construction Inc.				0	0	2	3	1	0	1	0	7	No
		580 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Soma Magnetics Corporation	585 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Nordstrom, Inc.	601 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Nelson-Keystone Inc. (aka Rreef management)	623 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
98	Anglin's Instrument Repair (aka Industrial Starters)	663 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
99	G.P. Precision	667 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1 1	0	7	No
100	Mike Harrison Construction, Inc.	667 S. State College Blvd. #79		92831	0	0	2	3	1	0	1	0	7	
	Airsoft Advantage (aka Machine Tool Factory)	679 S. State College Blvd.		92831	0	0	2		1	<u> </u>				No
	Micr Comp, Inc.						 	3	1	0	1 1	0	7	No
	Dzine Fab	689 S. State College Blvd. #A		92831	0	0	2	3	1	0	1	0	7	No
—	•	689 S. State College Blvd. Ste F	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Advanced Machine & Tool	699 S. State College Blvd. #F		92831	0	0	2	3	1	0	1	0	7	No
	Jarreau Signs	699 S. State College Blvd. Ste I	Fullerton	92831	0	0	2	3	1	0 -	1	0	7	No
107	Juniors Professional Iron	699 S. State College Blvd. Unit K	Fullerton	92831	0	0	2	3	* 1	0	1	0	7	No
110	Summit Event Productions	707 S. State College Blvd. Ste A		92831	0	0	2	3	1	0	1	. 0	7	No
111	Perfect Coat, Inc.	707 S. State College Blvd. Unit D		92831	0	0	2	3	1	n	1	0	7	-
,	Mica Lighting (aka Tiny's Forklift)	717 S. State College Blvd. # K		92831	0	0	2		1	<u> </u>				No
	Ken Thurm Enterprises (aka JCW Finishing; aka MRC Forklift, Inc.)	727 S. State College Blvd. # K		92831	<u> </u>			3	1	0	1	0	7	No
	ICW Finishing				0	0	2	3	1	0	1	0	7	No
		727 S. State College Blvd. Unit A		92831	0	0	2	3	1	0	1	0	7	No
	MRC Forklift, Inc.	727 S. State College Blvd. Ste C		92831	0	0	2	3	1	0	1	0	7	No
	Tiny's Forklift	733 S. State College Blvd. #98	1	92831	0	0	2	.3	1	0	1	0	7	No
	96 Upholstery (aka Industrial Starters)	737 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Auto Craft by Rick	743 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
122	Gasss	747 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
123	Industrial Starters	751 S. State College Blvd.	Fullerton		0	0	2	3	1	0	1	0	7	No
	AES Electronics Recycling, Inc. (aka Bright Polishing, Inc.; aka Advanced E-Waste				. •						<u> </u>	0		NO
	Solutions)	751 S. State College Blvd. Ste. 44	Fullerton	02021	0	o	ا ،	_			_		_	1
12.7	Solutions	751 5. State College Bivd. Ste. 44	Fullerton	32031	U	U	2	3	1	0	1	0	7	No
125	Overtical Circuity													1 1
	OneTech Circuit Inc.	753 S. State College Blvd. Unit 30	Fullerton		0	0	2	3	1	0	1	0	7	No
	Tiny's Forklift	759 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Pho Ellie (aka Fortress Foto Finishing; aka State College Quickprint)	765 S. State College Blvd.	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
129	Creative Machining, Inc.	765 S. State College Blvd. Ste D	Fullerton	92831	0	0	2	3	1	0	1	0	7	No
	Tri Pacific Heating & Air Conditioning (aka Span O Matic, Inc.; aka Quality Industrial										_			
		2116 E. Walnut Ave.	Fullerton	92831	1 [0	o	3	2	_	,	_	7	, Na
	Nordstrom, Inc. #391 (aka Nordstrom Design Center)	2200 E. Walnut Ave.		92831	1	0 .	0	3		0				No
	Anderson Air Conditioning LP	2100 E. Walnut Ave.							1	-	2	0	7	No
				92831	1	0	0	3	1	0	1	0	6	No
		2340 E. Walnut Ave.	Fullerton		0	0	0	3	1	0	2	0	6	No
36	PCA Metals	1723 E. Kimberly Ave.	Fullerton	92831	1	0	2	0	0	0	1	0	4	No
			<u> </u>	<u> </u>										
	Table 2: Project Priority Chart													
▍┝──		<u> </u>												
 	·													
											-			
			1											
▋└──┴			1											

Table 3

Key Parameter Concentrations in Well No.FM-8 (Source: OCWD)

Table 3
Monitoring Well FM-8 Key Parameter Concentrations
North Basin Groundwater Protection Project

		FM-8	
Permit Discharge Limit (ug/l)	Minimum (ug/l)	Mean (ug/l)	Max (ug/l)
6	3.0	20.20	55.8
5	16.5	32.43	64.5
5	30.8	49.44	91.6
3	ND	1.52	2.0
	Discharge Limit (ug/l) 6 5	Discharge (ug/l)	Permit Minimum (ug/l)

Notes:

⁽a) Mean of data in OCWD database for May 2001 through April 2010 Concentrations of non-detected (ND) compounds set at 1/2 detection limit

⁽b) Values are based on numerous rounds of sampling.

Table 4

Key Parameter Concentrations in Monitoring Wells (Source: OCWD)

 Table 4

 Surrogate Monitoring Wells, Key Parameter Concentrations, and Pumping Scenarios Used for Influent Concentration Calculations

 North Basin Groundwater Protection Project

			EW-1		EW-2		EW-3		EW-4		-2A
Surrogate Monitoring Well		FM-16		FM-15A		FM-11		FM-7		FM-18A ^c	
	Permit Discharge Limit	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/l)	Max ^b (ug/i)	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/i)	Max ⁶ (ug/l)
Primary VOCs (ug/l)									W-0 (P		
1,1-Dichloroethene (1,1-DCE)	6	0.025	0.05	4.4	5.0	1.7	2.1	37.40	46.00	1.30	1.30
Tetrachloroethene (PCE)	5	80/1	93,8	1.1	1.6	0.9	1.2	12.00	134 Ment Court of the Party of	0.60	0.60
Trichloroethene (TCE)	5	1	1,1	75,9	82.5	34.4	35.6	10.10	14.50	56.10	56/10
1,2-Dichloroethane (1,2-DCA)	0.5 ^d	0.025	0.05	14	16	0.025	0.05	0.025	0.05	0.70	0.70
Emergent Chemicals (ug/l)					1 !					5.0.250.000.000.000.000.000	2017/07/01/01/01/09
1,4-Dioxane	3	0.05	0.1	1.4	1.8	0.75	1.0	6.90	8.80	0.05	0.1
Perchlorate	4 ^e	1.25	2.5	107	117	91	0.0	1.70	2.50	470	4770
1,2,3-TCP	0.005 ^d	0.002	0.005	2017 Market Street	0.010	0.010	0.010	0.002	0.005	0.002	0.005
Nitrate (N) (mg/l)	10ª	1.6	1.6	iği, I	1166	14.8	151	5.50	5.60	9.10	9.10
Assumed Pumping Rates	Total Pumping Rate (gpm)	(gpm)		(gpm)		(gpm)		(gpm)		(gpm)	
Scenario 1	4,000	800		8	00	86	00	RI	00	А	nn
Scenario 2	3,500	80	00		00	700		800		800 600	
Scenario 3	3,000	70	00		00	600		700		500	
Scenario 4	2,500	60	00	400		500		600		400	

Notes:

- (a) Mean of data in OCWD WRMS database for July 2003 through July 2005. Concentrations of non-detected compounds set at 1/2 detection limit.
- (b) Maximum of data in OCWD WRMS database for July 2003 through July 2005. Concentrations of non-detected compounds set at detection limit. (c) Values are based on numerous rounds of sampling.
- (d) Discharge limit for 1,2-DCA and nitrate not specified in RWQCB permit; Maximum Contaminant Level used as discharge limit.
- (e) Permit discharge limit expected to be raised to 6 ug/l, the current State Notification Level.

Parameters with concentrations shown in italics were not detected, but are listed because it was detected in one or more surrogate monitoring well. Shaded values exceed permitted discharge limit or assumed discharge limit.

Table 5

List of Sites Recommended for Site Screening or Site Re-assessment (Source:DTSC)

			1	T	Γ		T	1		· · · · · · · · · · · · · · · · · · ·		1		
						Site Known to	Site Lies							
						Have Used		Site Currently				Site with Large		
Мар					Site	Solvents on	Footprint of	Under	Number of			Volumes of		
Ref					Distance	Regular Basis/In-	Localized	Regulatory		PCE/TCE	D	1		
	Site Name	Address	City	Zip		Large Volume	Plume	Oversight		•	Property	Blank/Unknown		Site in
1.0.	Graphics Tech, LLC. (aka Graphic Techonology; aka American Electronics, Inc.; aka	Address	City	<u> </u>	II OIII FIVIO	Large volume	Plume	Oversight	Operation	Confirmation	Size	Disposed	TOTAL	CERCLIS
141	Graphics 2000)	1600 E. Valencia Dr.	Fullerton	92831	3	3	2	_						İ
	S C I F Fullerton, LLC. (aka Weber Aircraft; aka Monogram Systems; aka Weyerhaeser	1000 L. Valencia Dr.	Fullerton	92031		3	<u> </u>	3	3	2	2	2	20	No
	Company)	1300 E. Valencia Dr.	Fullerton	02624	•						_	_		
	National Technical Systems, Inc.	1536 E. Valencia Dr.		92634	3	3	2	3	3	2	2	2	20	No
66	Terra Universal, Inc. (aka California Shirt Sales)	800 S. Raymond Ave	Fullerton	92831	3	3	2	3	3	0	2	2	18	No
69	Orange County Paint		Fullerton	92831	22	3	2	3	3	0	2	2	17	No
35	Orange County Metal Processing	1710 E. Rosslynn Ave.		92831	2	3	2	3	3	0	2	2	17	No
33		1711 E. Kimberly Ave.	Fullerton	92831	2	3	2	3	3	0	2	2	17	No
63	Mesa Cold Storage, Ltd (aka Frozsun Food; aka New West Foods, aka AmeriCold	700 6 5				_								
62	Logistics; aka Cleugh's Rhubarb Company; aka AmeriCold)	700 S. Raymond Ave.	Fullerton	92831	2	3	2	3	2	0	2	2	16	No
22	Ruan Transportation Corporation (aka Johnson Controls Battery Group, Inc.; aka Ruen											1	ļ ·	
33	Leasing Co.; aka Southern California Edison; aka J&V Cartage)	1550 E. Kimberly Ave.	Fullerton	92831	2	3	2	0	3	2	2	2	16	Yes
20	Kryler Corporation	1217 E. Ash Ave.	Fullerton	92831	3	3	. 2	. 3	3	0	0	2	16	No
	BC2 Environmental Rental (aka Avory Streech; aka Atlas Copco, Inc.; aka Prime Energy	1												
19	Systems)	1212 E. Ash Ave.	Fullerton	92631	3	3	2	3	3	0	0	2	16	No
	Omni Optical (aka Omni Optical Products, Inc.; aka Coca Cola Foods; aka Nutri-Foods													
5	International, Inc.)	360 S. Acacia Ave.	Fullerton	92831	2	3	2	3	2	2	2	0	16	No
	St Hart Container Corporation, Division of Subclipse (aka St. Hart Container													
72	Corporation)	1901 E. Rosslynn Ave.	Fullerton		1	3	2	3	3	0	2	2	16	No
70		1726 E. Rosslynn Ave.	Fullerton	92831	2	3	2	0	3	2	2	2	16	No
	Tops Auto Body (aka K&N Automotive; aka Trinity Auto Collision Inc.; aka Honda Car													
44	Specialty)	500 S. Raymond Ave. Unit C	Fullerton	92831	3	3	2	3	3	0	2	0	16	No
73	Corru-Kraft, Co. (aka Corru-Kraft, Inc.)	1911 E. Rosslynn Ave.	Fullerton	92831	1	3	2	3	3	0	2	2	16	No
	YRC Enterprise Services DBA USF Reddaway (aka EDO Corp, Western Div ; aka													
74	USF/Reddaway; aka Gulton Industries; aka Bud's Delivery Inc.)	300 S. State College Blvd.	Fullerton	92831	0	3	0	3	3	2	2	2	15	No
				İ					i					
150	FBI Express, Inc. (aka U.S. Delivery; aka Todd Pollock; aka American Fleet Service)	1250 E. Walnut Ave.	Fullerton	92831	3	o	2	3	3	0	2	2	15	No
14	UPS Freight (aka Overnite Transportation)	650 S. Acacia Ave.	Fullerton	92831	2	3	2	3	1	0	2	2	15	No
157	Kraft Foods, Inc. (aka Kraft Foods; aka Claussen Pickle Co.; aka Nalco Chemical; aka	1500 E. Walnut Ave.		92831	3	0	2	3	3	0	2	2	15	No
	Inland Computer Products (aka Beckman Instruments; aka Allergan)	1410 E. Walnut Ave.	Fullerton	92831	3	0	2	3	3	2	2	0	15	No
64	Performance Envelope Co.	711 S. Raymond Ave. Unit B		92831	2	3	2	3	2	<u> </u>	1	2	15	No
75	Kairak aka Don Green's Sales Inc.			92831	0	3	2	3	3	0	2	2	15	No
42	Top Auto Repair (aka LG Knox Construction; aka Terry's Automotive)			92831	3	3	2	3	2	0	0	2	15	No
		0 00 - 0.25 mile = +3				-							1.7	140
		0.25 - 0.50 mile = +2		[ļ
		0.50 - 0 75 mile = +1												
1	Site Distance from FM-8 well	0.75 - 1.00 mile = +0												
	Is the site known to have used solvent on a regular basis?	Yes = +3; No = +0			-									
	Does the site lie within the footprint of a localized plume?	Yes = +2; No = +0												
		Yes = +0												
4	Is the site currently under a regulatory order for investigative or remedial action?	No = +3		İ										Į
<u> </u>		21 years or more = +3	1											
		11 - 20 years = +2]			+				
₅		11 - 20 years = +2 0 - 10 years = +1			İ									
		Ves = +2; No = +0				*								
		Large (> 1 acre) = +2				j					İ			İ
7		Medium (0 25 - 1.0 acre) = +1			İ					İ				
		Small (< 0.25 acre) = 0												
,		Yes = +2				-		į		f				
8		No = +0												
	Table 5: List of Sites Recommended for Site Screening/Reassessment													
				<u>l</u> -	1							·		

FIGURES




Figure 1

LINK TO THIS MAP | ENVIROSTOR HOME | MANAGE PROJECTS | REPORTS | SEARCH | LOGOUT LAYERS ✓ ■ Federal Superfund ✓ State Response ✓

✓ Voluntary Cleanup ☑ School Cleanup ✓ ■ Evaluation ☑ School Investigation ✓ Military Evaluation ✓ □ Tiered Permit ✓ ■ Corrective Action ✓ ● Haz Waste Permit △ GeoTracker LUFT △ GeoTracker SLIC Public Water Wells MAP SIZE 640x480 15 Sites

SITE LIST

Figure 2
North OC Site Discovery Project Area

ATTACHMENTS

SITE DISCOVERY WORKPLAN

North Orange County Project: DTSC - Cypress Branch

Cooperative Agreement No. V-97999001-2

December 6, 2010

Prepared for: Mr. Carl Brickner
U.S. Environmental Protection Agency
Region 9

Prepared by: Rafiq Ahmed
Cal/EPA Department of Toxic Substances Control
5796 Corporate Ave. Cypress, CA 90630

Signatures and Concurrence:

Signature	Greg Holmes Type Name	12/6/10 Date: (MM/DD/YYY)
Signature	/ Carl Brickner Type Name	12/22/2010 Date: (MM/DDYYYY)
	DYZ	Signature Type Name / Carl Brickner

List of Acronyms

DTSC: Department of Toxic Substances Control RWQCB: Regional Water Quality Control Board

CERCLA: Comprehensive Environmental Response, Compensation, and Liability Act

SARA: Superfund Amendments and Reauthorization Act

EPA: U.S. Environmental Protection Agency

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information

System

North OC: North Orange County

1.0 Introduction

Under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA), the California Environmental Protection Agency, Department of Toxic Substances Control (DTSC), Cypress Region has been tasked to conduct a Site Discovery Project for the North Orange County (North OC), California area.

More information about the Superfund program is available on the EPA web site at http://www.epa.gov/superfund

2.0 Site Description

The North Orange County (OC) Site Discovery Project will be conducted in the southern portion of the city of Fullerton (**Figure 1**) in Orange County, California. The purpose of this project is to identify potential sources of groundwater contamination which have caused the closure of four production wells and threatened several other production wells. **Table 1** shows contaminant concentrations in extraction wells in the project area

DTSC's project builds on the efforts of the Orange County Water District (OCWD) to identify sources of groundwater contamination. The study area for OCWD's North Basin Groundwater Protection Project includes the area of DTSC's North OC Site Discovery Project. The study area of the North OC Site Discovery Project (Project Area) is bounded by South State College Boulevard to the east, E. Commonwealth Avenue and S. Lillie Avenue to the north-east, S. Raymond Avenue to the west, E. Walnut Avenue to the north, and E. Kimberly Avenue to the south (Figure 2). This area was chosen because it may contain one or more sources of groundwater contamination contributing to a regional plume and impacting well No. FM-8, a monitoring well operated by OCWD. The maximum concentrations of trichloroethene (TCE), tetrachloroethene (PCE), 1,1-Dichloroethene (1,1-DCE) and 1,4-Dioxane detected in well No. FM-8 (Table 2) were 91 6ug/l, 64.5 ug/l, 55.8 ug/l and 2 ug/l respectively, for the period of May 2001 through April 2010. Groundwater in the Project Area generally flows to the west, in the direction of well No. FM-8. Currently the source of contamination in FM-8 is unknown.

2.1 Hydrogeologic Setting

Various investigations conducted by Orange County Water District (OCWD) and others have revealed that groundwater in the northern portion of the Orange County groundwater basin, generally north of the 91 Freeway, west of the 57 Freeway, east of Magnolia Avenue, and south of Chapman Avenue, is contaminated with VOCs that are constituents of industrial degreasing solvents. This approximately 11-square-mile area is located in the cities of Fullerton and Anaheim, and falls within the region known as the Forebay, which is the predominant area of basin recharge. For the purposes of this report, this area will be referred to as the North Basin Area, as depicted on Figure 1.

Groundwater contamination in the project area is primarily found in the shallow-most aquifer, which is generally less than 200 feet deep. However, in the eastern North Basin area, VOC-impacted groundwater has migrated downward and into aquifers tapped by production wells. To protect public health, the City of Fullerton shut down production wells F-FS13 and F-KIM1 in 1999 and 2001, respectively, as a result of increasing tetrachloroethene (PCE) concentrations. These wells were subsequently destroyed in 2002. Groundwater contamination originating in the shallow aquifer continues to migrate both laterally and vertically in response to hydraulic gradients in the area. Both shallow and deeper monitoring wells along the downgradient edges of the VOC plumes exhibit significantly increasing VOC concentrations, demonstrating that the plumes continue to migrate. The groundwater monitoring data show that downgradient production wells operated by the cities of Fullerton and Anaheim are threatened if the VOC-impacted groundwater continues to migrate unabated into the deeper aquifers where the bulk of groundwater production takes place. Also, continued migration of contamination will adversely impact the water producer's ability to utilize contaminated parts of the aquifer.

2.2 Operational History of Major Sites in the North Basin

For decades, much of the North Basin area has had overlying industrial land use Numerous industrial facilities have contributed to groundwater contamination in the area. The California Regional Water Quality Control Board, Santa Ana Region (RWQCB) identified several facilities responsible for groundwater contamination in the North Basin and has taken actions to address contamination at some specific facilities. All of these sites are associated with groundwater contamination plumes that are suspected to have been caused by past and present chemical handling practices. A groundwater plume map from what OCWD terms "high risk" sites is shown in **Figure 3**

3.0 Apparent Problem

Groundwater is the primary source of drinking water in Orange County, supplying about 80 percent of all drinking water. This water supply has been threatened by two large multi-source groundwater plumes: one mostly in Santa Ana in central Orange County and other in north Orange County in the Fullerton area, which is the subject of this Site Discovery Project. These two Orange County plumes are separated by several miles and are not contiguous.

DTSC and the Regional Water Quality Control Board (RWQCB) have been aware of groundwater contamination at various sites in the Project Area since the 1980s, but there does not appear to have been a regional approach to the problem until the Orange County Water District (OCWD) initiated its North Basin Groundwater Protection Project in 2005

The North Basin contains several production wells that are threatened by the contamination plume; 80% of Fullerton's water is from the wellfield and most of the plume is in Fullerton which has already lost two production wells. These wells contain high levels of tetrachloroethene (PCE), trichloroethene (TCE) and perchlorate, and have been taken offline Other chemicals found in the groundwater plume include 1,1-DCE, and 1,4-dioxane, primarily in the shallow groundwater zone

4.0 Proposed Solution

OCWD has investigated groundwater conditions in the North Basin Area, and has prepared and updated a focused feasibility study to address groundwater contamination in the North Basin Area, and has filed lawsuits naming companies suspected to be sources of the VOC and/or perchlorate contamination DTSC's task is to review database information and site files, and conduct file search and field surveys, to discover any additional potential contamination source sites. Any additional identified sites will be added to a project database together with other relevant information DTSC proposes the following sources of information and methodology

5.0 Sources of Information

- 1 U.S. EPA's CERCLIS database will be checked for site status (active, archived, or not in CERCLIS) The Project database will indicate which sites are in CERCLIS, so DTSC can separate the list into sites for future screening and reassessment.
- DTSC's Hazardous Waste Tracking System will be reviewed to identify generators of hazardous waste containing VOCs or potentially containing VOCs and to add those sites to the list.
- 3 DTSC's EnviroStor database, the RWQCB's Geotracker database, and the Orange County Health Care Agency (OCHCA) sites list will be checked to see which sites are in those programs. A limited file review may also be conducted if necessary
- 4. Compiled evidence will be reviewed to identify sites with confirmed contamination, for future enforcement if necessary. This will include groundwater sampling data if available.
- 5. A drive-by survey will be conducted to identify additional potential sites and add sites to the list, after steps #1-4 have been conducted.

6.0 Methodology

A project database will be compiled Based on collected information, sites will be scored for future site screening and reassessment. Sites identified for screening will be added to the current EPA's monthly tracking report (MRTR) for screening, either during this fiscal year or next fiscal year.

7.0 Regulatory Agencies

7.1 U.S. Environmental Protection Agency (EPA)

EPA's CERCLIS database will be reviewed. Sites in CERCLIS will be flagged in the project database and some of them will be designated for potential site reassessment instead of site screening, since site screens are performed only on sites that are not in CERCLIS

7.2 Department of Toxic Substances Control (DTSC)

Sites will be checked against DTSC's EnviroStor database. For sites in EnviroStor, the information will be used to populate the "detections of chemicals of concern" field of the project database and, if possible, the "confirmation confirmed" field DTSC's HAZNET database will be reviewed for manifest information on types and volumes of waste streams and any cleanup waste shipped off site. This site discovery project has been

incorporated into the work of the Cypress Cleanup Program Orange County Groundwater Cleanup Team The charter for this team is included as Appendix 1

7.3 Regional Water Quality Control Boards (RWQCBs)

The Regional Water Quality Control Boards' (RWQCB) Geotracker database will be reviewed. For sites in EnviroStor, the information will be used to populate the "detections of chemicals of concern" field of the project database and, if possible, the "confirmation confirmed" field.

7.4 Certified Unified Planning Agencies (CUPAs)

A list of sites in the Project Area and contamination information will be requested from the Orange County Health Care Agency (OCHCA), the CUPA for Orange County

7.5 Orange County Water District (OCWD)

The OCWD was established by the state legislature in 1933 to protect the water resources of Orange County and to represent the County's water purveyors. OCWD monitors groundwater wells, collects water quality data, and coordinates the use of groundwater in the County. OCWD initiated the North Basin Groundwater Protection Project in an effort to address groundwater contamination in the Fullerton area. DTSC has attended several meetings with OCWD in which this Site Discovery Project was discussed, among other topics. OCWD provided DTSC with a list of 40 defendants that OCWD believes may be sources of groundwater contamination of the North Basin; a Composite VOC Plume Map -January 2009 (Figure 3); and Excel spreadsheets listing VOC contaminations detected in public wells

8.0 Deliverable

DTSC will produce and finalize a Site Discovery Report, according to the approved Workplan for the North Orange County Site Discovery Project. DTSC's target submittal date is by December 31, 2010. The final report will include the project database which will list the sites identified by DTSC, and their priority for future site screening. The highest priority sites will be included in this year's PA/SI Workplan (MRTR) with the remainder to be screened during fiscal year 2011-2012

TABLES

Table 1 - Contaminant Concentrations in Extraction Wells (Source: OCWD)

Table 2 - Contaminant Concentrations in Well No. FM-8 (Source: OCWD)

FIGURES

Figure 1 - General Project Area (Source: DTSC with OCWD consultation)

Figure 2 - Project Area Map (Source: DTSC EnviroStor)

Figure 3 - Composite VOC Plume Map (Source: OCWD)

ATTACHMENTS

Attachment 1- TCE, PCE, 1, 1 - DCE Concentrations in Well No. FM-8 (Source: OCWD)

APPENDICES

Appendix 1 - DTSC Orange County Groundwater (OCGW) Team Charter (Source: DTSC, OCGW Team)

TABLES

Table 1 Surrogate Monitoring Wells, Key Parameter Concentrations, and Pumping Scenarios Used for Influent Concentration Calculations North Basin Groundwater Protection Protect

		EM	/-1	EV	V-2	EW-3		EW-4		EW-2A	
Surrogate Monitoring Well		FM-16		FM-15A		FM-11		FM-7		FM-18A°	
	Permit Discharge Limit	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/l)	Max ^b (ug/l)	Mean ^a (ug/l)	Max ^b (ug/l)
Primary VOCs (ug/l)					**************************************						-
1,1-Dichloroethene (1,1-DCE)	6	0.025	0.05	4.4.	5.0	1.7	2.1	37.40	26.00	1.30	1.30
Tetrachloroethene (PCE)	5	# 80m #	- 93,8	1.1	1.6	0.9		12.00	3.80	0.60	0.60
Trichloroethene (TCE)	5	1	1,1	75.9	82.5	344		#19.10 H	1450		56 10
1,2-Dichloroethane (1,2-DCA)	0.5 ^d	0.025	0.05	14	116	0.025	0.05	0.025		0.70	
Emergent Chemicals (ug/l)											
1,4-Dioxane	3	0.05	0.1	1.4	1.8	0.75	1.0	6.90	8.80	0.05	0.1
Perchlorate	4 ^e	1.25	2.5	10.7		i	99	1.70			4.70
1,2,3-TCP	0.005 ^d	0.002	0.005		o o ro		0.010	0.002	0.005	0.002	0.005
Nitrate (N) (mg/l)	10 ⁴	1.6	1.6	101.	ile ile e	1,445	/16H	5.50	5.60	9.10	9.10
Assumed Pumping Rates	Total Pumping Rate (gpm)	(gr	om)	(gpm)		(gpm)		(gpm)		(9)	om)
Scenario 1	4,000	800		8	00	80	00	8	00	8	00
Scenario 2	3,500	8	00	6	00	700		800			00
Scenario 3	3,000	7	00	500		600		700		500	
Scenario 4	2,500	6	00	400		500		60D		400	
Notes:										<u> </u>	

- (a) Mean of data in OCWD WRMS database for July 2003 through July 2005. Concentrations of non-detected compounds set at 1/2 detection limit.
- (b) Maximum of data in OCWD WRMS database for July 2003 through July 2005. Concentrations of non-detected compounds set at detection limit.
- (c) Values are based on one round of sampling.
- (d) Discharge limit for 1,2-DCA and nitrate not specified in RWQCB permit; Maximum Contaminant Level used as discharge limit.
- (e) Permit discharge limit expected to be raised to 6 ug/l, the current State Notification Level.

Parameters with concentrations shown in italics were not detected, but are listed because it was detected in one or more surrogate monitoring well. Shaded values exceed permitted discharge limit or assumed discharge limit,

Table 2
Monitoring Well FM-8 Key Parameter Concentrations
North Basin Groundwater Protection Project


Monitoring Well	FM-8					
	Permit Discharge Limit	Minimum (ug/l)	Mean (ug/l)	Max (ug/l)		
Primary VOCs (ug/l)						
1, 1-Dichloroethene (1, 1-DCE)	6	3.0	20.20	55.8		
Tetrachloroethene (PCE)	5	16.5	32.43	64.5		
Trichloroethene (TCE)	5	30.8	49.44	91.6		
Emergent Chemicals (ug/l)			,			
1, 4-Dioxane	3	ND	1.52	2.0		
		L				

Notes:

(a) Mean of data in OCWD database for May 2001 through April 2010 Concentrations of non-detected (ND) compounds set at 1/2 detection limit

(b) Values are based on numerous rounds of sampling

FIGURES







FIGURE 2



ATTACHMENTS

Attachment 1

	Well No. FM-8	Contaminant	Concentrations		
STATION	DATETIME	PARAMABBR	RESULT_TXT	RDL	UNITSABBR
FM-8/1	4/22/2010	11DCE	84	05	ug/L
FM-8/1	2/10/2010	11DCE	16 9	05	ug/L.
FM-8/1	10/21/2009	11DCE	15 6	0 5	ug/L
FM-8/1	7/15/2009	11DCE	26 2	05	ug/L
FM-8/1	4/6/2009	11DCE	31 9	0.5	ug/L.
FM-8/1	1/21/2009	11DCE	51 6	0.5	ug/L
FM-8/1	10/7/2008	11DCE	54 2	05	ug/L
FM-8/1	7/30/2008	11DCE	37 6	0.5	ug/L
FM-8/1	6/2/2008	11DCE	23 4	05	ug/L
FM-8/1	2/6/2008	11DCE	38 7	0.5	ug/L
FM-8/1	12/10/2007	11DCE	55 8	05	ug/L
FM-8/1	8/8/2007	11DCE	11 5	05	ug/L
FM-8/1	5/22/2007	11DCE	12 3	05	ug/L
FM-8/1	2/8/2007	11DCE	13.9	05	ug/L
FM-8/1	11/16/2006	11DCE	18	05	ug/L
FM-8/1	5/11/2006	11DCE	30 4	05	ug/L
FM-8/1	2/7/2006	11DCE	27 6	05	ug/L
FM-8/1	12/1/2005	11DCE	11 1	05	ug/L
FM-8/1	12/1/2005	11DCE	11 3	05	ug/L
FM-8/1	6/1/2005	11DCE	12 8	05	ug/L
FM-8/1	4/21/2005	11DCE	61	05	ug/L
FM-8/1	5/24/2004	11DCE	89	05	ug/L
FM-8/1	2/1/2003	11DCE	45	05	ug/L
FM-8/1	6/25/2002	11DCE	56	05	ug/L
FM-8/1	11/7/2001	11DCE	3.2	0.5	ug/L
FM-8/1	8/21/2001	11DCE	3	05	ug/L
FM-8/1	5/10/2001	11DCE	56	05	ug/L
[-]VI=O/ I	5/10/2001	TIDGE	30	0.5	ug/L
FM-8/1	4/6/2009	14DIOX	ND	1	ug/Ļ
FM-8/1	1/21/2009	14DIOX	ND	1	ug/l.
FM-8/1	7/30/2008	14DIOX	ND	1	ug/L
FM-8/1	6/2/2008	14DIOX	ND	1	ug/L
FM-8/1	2/6/2008	14DIOX	ND	1	ug/L.
FM-8/1	12/10/2007	14DIOX	ND	1	ug/L
FM-8/1	8/8/2007	14DIOX	ND	1	ug/L
FM-8/1	2/8/2007	14DIOX	ND	1	ug/L
FM-8/1	11/16/2006	14DIOX	ND	1	ug/L
FM-8/1	2/7/2006	14DIOX	ND	1	ug/L
FM-8/1	12/1/2005	14DIOX	ND	1	ug/L
FM-8/1	6/1/2005	14DIOX	ND .	1	ug/L
FM-8/1	4/21/2005	14DIOX	ND	1	ug/L
FM-8/1	5/24/2004	14DIOX	ND	1	ug/L
FM-8/1	2/1/2003	14DIOX	ND	1	ug/L
FM-8/1	6/25/2002	14DIOX	13	1	ug/L
FM-8/1	11/7/2001	14DIOX	ND	1	ug/L
FM-8/1	8/21/2001	14DIOX	2	1	ug/L
FM-8/1	4/22/2010	PCE	37 8	0.5	ug/L
FM-8/1	2/10/2010	PCE	182	0.5	ug/L
1 141-0/ t	2/ 10/20 10	FOL	102	Ų U	~9, <u>-</u>

	FM-8/1	10/21/2009	PCE	19.8	0 5	ug/L				
	FM-8/1	7/15/2009	PCE	26 3	05	ug/L ug/L				
	FM-8/1	4/6/2009	PCE	16 7	05	ug/L ug/L				
			PCE							
	FM-8/1	1/21/2009		18 4	05	ug/L				
	FM-8/1	10/7/2008	PCE	27 4	05	ug/L				
	FM-8/1	7/30/2008	PCE	29 4	05	ug/L				
	FM-8/1	6/2/2008	PCE	22 8	0.5	ug/L				
	FM-8/1	2/6/2008	PCE	37 3	05	ug/L				
	FM-8/1	12/10/2007	PCE	59 8	05	ug/L				
	FM 8/1	8/8/2007	PCE	16 5	05	ug/L				
	FM-8/1	5/22/2007	PCE	20 9	0.5	ug/L				
	FM-8/1	2/8/2007	PCE	26 6	0.5	ug/L				
	FM-8/1	11/16/2006	PÇE	29 8	0.5	ug/L				
	FM-8/1	5/11/2006	PCE	55 3	0 5	ug/L				
	FM-8/1	2/7/2006	PCE	64 5	0.5	ug/L				
	FM-8/1	12/1/2005	PCE	34 5	0 5	ug/L				
	FM-8/1	12/1/2005	PCE	37 6	05	ug/L				
	FM-8/1	6/1/2005	PCE	40 2	05	ug/L				
	FM-8/1	4/21/2005	PCE	30 1	0.5	ug/L				
	FM-8/1	5/24/2004	PCE	33 1	0 5	ug/L				
	FM-8/1	2/1/2003	PCE	38	05	u g/L		*		
	FM-8/1	6/25/2002	PCE	48 1	0 5	ug/L				
	FM-8/1	11/7/2001	PCE	24	05	ug/L				1
	FM-8/1	8/21/2001	PCE	30 1	0 5	ug/L				
	FM-8/1	5/10/2001	PCE	35 4	0 5	ug/L				
	FM-8/1	4/22/2010	TCE	33 6	0.5	ug/L				
	FM-8/1	2/10/2010	TCE	32 8	0.5	ug/L				
	FM-8/1	10/21/2009	TCE	30 8	0.5	ug/L				
	FM-8/1	7/15/2009	TCE	36 2	0.5	ug/L				
	FM-8/1	4/6/2009	TCE	34 9	0.5	ug/L				
	FM-8/1	1/21/2009	TCE	52 1	0.5	ug/L				
	FM-8/1	10/7/2008	TCE	49	0.5	ug/L				
	FM-8/1	7/30/2008	TCE	47 3	05	ug/L				
	FM-8/1	6/2/2008	TCE	43 6	05	ug/L				
	FM-8/1	2/6/2008	TCE	62 9	05	ug/L				
•	FM-8/1	12/10/2007	TCE	916	05	ug/L				
	FM 8/1	8/8/2007	TCE	54 7	0.5	ug/L			•	
	FM-8/1	5/22/2007	TCE	55 9	0.5	ug/L				1
	FM-8/1	2/8/2007	TCE	58 6	05	ug/L				1
	FM-8/1	11/16/2006	TCE	52 6	05	ug/L ug/L				
	FM-8/1	5/11/2006	TCE	64 6	0.5	ug/L ug/L				
	FM-8/1	2/7/2006	TCE	60 9	0.5	ug/L ug/L				
	FM-8/1	12/1/2005	TCE	50 g	05	ug/L ug/L				Tracket Land
	FM-8/1	12/1/2005	TCE	49 3	05	ug/L ug/L				
	FM-8/1		TCE	49 3 43 7	05	ug/L ug/L				
		6/1/2005			05					
	FM-8/1	4/21/2005	TCE	36 2 34 1		ug/L				
	FM-8/1	5/24/2004	TCE	34 1	05	ug/L				
	FM-8/1	2/1/2003	TCE	47 4	05	ug/L				
	FM-8/1	6/25/2002	TCE	40 7	05	ug/L				
	FM-8/1	11/7/2001	TCE	46 5	05	ug/L				
	FM-8/1	8/21/2001	TCE	54 8	0 5	ug/L				
							·			İ

FM-8/1

5/10/2001

TCE

56 9

APPENDICES



Department of Toxic Substances Control Region 4 P2dW/Orange County Groundwater (OCGW) Team

OCGW Team Charter April 2010

Sponsors: Ray Leclerc, Assistant Deputy Director

John Scandura, Performance Manager

Advisors: Scott Warren, P2dW Team Leader

Ted Peng, Agency Coordination/MOU Negotiation

J.T. Liu, Special Task Advisor

Leader: Greg Holmes

Members:

Eileen Khachatourians, Lead Project Manager (PM) and PM for Orange County North (OCN)

Robert Romero, PM Orange County Central (OCC)

Rafiq Ahmed, PM and site discovery PM

CY Jeng and Efrem Neuwirth, Toxicology

Jackie Spiszman, Project consultant

Debbie Schwartz, Legal

Kathie Schievelbein, CEQA

Paul Pongetti and Jim Wilkinson, Geology

Sara Michael, GIS/Data Base/EnviroStor

Steven Hariri, Engineering

Tim Chauvel, Public Participation

Decision making and its involved fundamental processes will be self-directed, transparent and made by team consensus

OCGW Team Role:

- 1 To better protect groundwater in Orange County, public health and safety, environmental and technical aspects of projects will be focal points
- Establish collaborative, long term, relationships with various agencies such as the State Water Resources Control Board (SWRCB), the Los Angeles and Santa Ana Regional Water Quality Control Boards (LARWQCB and SARWQCB respectively), the Orange County Water District (OCWD), the Water Replenishment District (WRD), responsible parties (RPs) and the citizens of affected communities by promoting open and transparent communication
- 3 Bring disparate groups together to identify and resolve soil and groundwater contamination issues and to promote efficient use of limited resources

- 4 Present demonstration projects to DTSC staff, management and legislators during internal workshops and at technical conferences
- Develop and implement a regional Conceptual Model focusing on cost effective characterization and remediation of groundwater contamination, while simultaneously identifying potential source areas
- 6 Address interim measures during source removal activities
- 7 Compile information, analyze data and publish maps using GIS technology
- 8. Focus site discovery efforts by identifying potential RPs (PRPs), negligent and other parties responsible for groundwater contamination
- 9. Align project activities with the DTSC Strategic Plan and P2dWs tactical agenda
- 10. Coordinate CEQA activities
- 11 Prioritize, and improve efficiency of project activities to protect ground water resource
- 12 Encompass more cost effective solutions by expanding both professional and technical perspectives beyond individual site boundaries
- 13. Work with RPs to ascertain and implement win/win solutions
- Seek constructive feedback from both internal and external customers to enable continuous improvement

Vision: To create "Social Capital," a community in which disparate groups join to actively participate in the protection and preservation of Orange County's groundwater. To focus on discovery, design and implementation of the best project management practices for site characterization and remediation and to improve efficiencies of regulatory oversight to protect groundwater resources in Orange County

Mission: To promote integration of water protection and management activities, structured to develop innovative solutions to complex multi-disciplinary environmental problems. Driven to efficiently and effectively safeguard Orange County's ground water thereby protecting the critical drinking water supply

Core Values: Create and maintain a trusting, open, communicative environment; an environment where disparate groups, with varying perspectives and interests may come together to express concerns and opinions. A place where trepidations are acknowledged and discussed, as all parties invest themselves in the development of creative, responsible, "win-win" solutions to complex environmental problems that either impact or may impact Orange County's ground water

Proposed Approach

- Collect groundwater, soil and lithology data as well as other important information from contaminated Sites and impacted drinking water wells to ascertain and apply the best management practices and approaches necessary and available to protect ground water thereby shielding Orange County's drinking water from potential toxic harm
- Secondly, work to maximize the use of stakeholder and taxpayer monies by considering and utilizing collaborative approaches developed through

- partnerships with other agencies, water districts and various stakeholders to ultimately protect drinking water
- Thirdly, examine the environmental cost verses benefit of clean-up (the net environmental gain) and reevaluate the approaches being utilized to protecting Orange County's ground/drinking water for all consumers
- Lastly, the OCGW Team will look for new innovative, cost effective, approaches
 to protecting California's drinking water resources and consumers/users.

Strategic Goals, Objectives, Outputs & Outcomes (Measures)

- Goal 1: OCGW Team projects and activities are intended to be transparent and time and cost predictable to: maximize public health protection, conserve natural resources, provide environmental stewardship and advance property reuse.
- Objective 1.1 Develop groundwater cleanup initiatives
- Strategy 1 1.1 Identify and define the problem: contaminants, source, areas and media affected

Perform site discovery seeking RPs and PRPs of contaminated and potentially contaminated sites

Compile and analyze data and communicate results

Output 1.1.1-1 Collaborate with the SWRCB, LARWQCB, SARWQCB, and OCWD, and the WRD in order to share methodologies, data and resources

Rank and prioritize the groundwater supply wells and monitoring wells according to use, need, service area and impact

Evaluate the most cost effective methods to characterize, remediate and protect limited groundwater resources and public drinking water

Output 1.1.1-4 Work proactively with various agencies and purveyors in determining lead agency status

Develop an expedited process for identifying sources of impacts to groundwater and drinking water wells

Protect and preserve groundwater, drinking water wells and surface water resources

Outcome 1.1.1-4 Reduce both the costs and risks associated with remediation of contaminated groundwater for stakeholders and consumers

Areas of Concern:

Orange County Central (OCC) – Santa Ana Area Orange County North (OCN) – Fullerton Area

OCGW Team Project Duration: June 2009 through June 2011. At completion of project team period, the OCGW Team will re-assess the goals and accomplishments, and evaluate revisions to the P2dW/OCGW Team charter, if necessary

Tasks:

- Site discovery (EPA PA/SI) Identify unknown sites in the OCN and OCC areas
- Assist OCWD in identifying and evaluating potential responsible parties (PRPs)
- Develop community based approach and strategies to investigate, monitor, and cleanup of regional groundwater contamination.
- Establish regional groundwater task force: DTSC, SWRCB, LARWQCB, SARWQCB, OCWD, WRD, RPs, PRPs, local Water Purveyors and Districts to cooperate and effectively address regional contamination issues of plume identification, stabilization and remediation.
- Evaluate CEQA processes and needs

Project Scope and Deliverables:

- Joint Memorandum of Understanding (MOU) with , the United States Environmental Protection Agency (USEPA), SWRCB, LARWQCB, SARWQCB, OCWD, and other (local) city and county agencies
- Develop <u>consent orders and</u> corrective action consent agreements with known RPs of operating facilities in focused areas of concern
- Prepare enforcement orders and or other regulatory actions to serve upon recalcitrant RPs
- Issue corrective action consent and or enforceable agreementsconsent orders to PRPs
- Utilize DTSC voluntary clean-up programs and other enforcement strategies to facilitate and expedite groundwater clean-up activities
- Implement consistent and compatible measures (interim and other) to address contamination of source areas and eliminate pathways to groundwater at all project sites
- regional groundwater models to simulate plume migrations and incorporate them into GIS or other visualization software
- Design regional groundwater control and cleanup strategies
- Develop and implement final remedies for regional groundwater plumes
- Recognize and address environmental issues and concerns by preparing appropriate CEQA documents for determining environmental impacts

Total Team PYs Estimate

Leader: Greg Holmes	0.40	PΥ	
Members: Eileen Khachatourians, PM Robert Romero, PM Rafiq Ahmed, PM Jackie Spiszman, Project consultant CY Jeng and Efrem Neuwirth, Toxicology Paul Pongetti, Geology Jim Wilkinson, Geology Debbie Schwartz, Legal Kathie Schievelbein, CEQA Sara Michael, GIS/Data Base/EnviroStor/SharePoint Tim Chauvel, Public Participation Steven Hariri, Engineering		0.50 0.50 0.25 0.20 0.50 0.25 0.25 0.30 0.20 0.10	PY PY PY PY PY PY PY PY
	Total:	4 00	PΥ

P2dw Team Stakeholder Needs Pentagon

(revised 3/26/09)

Design Intent:

Apply an Effective Efficient Safe & Economical Approach to P2div


Funding/Business Needs

- Reduce cost (time)
- Increase Efficiency,
- · Increase profits, benefits & value
- ID and pursue Funding Opportunities (Prop 84?) (Stakeholders: Developers, RPs, Redevelopment Agencies Property Owners Orphan Sites)

Political Needs

- Community Protection, Effective Remedies, (Demonstration Projects) Legislative Scorecard
- Tax Revenue
- · Jobs
- · Environmental Justice
- Make maps to show issues
- Develop DTSC Branding,
 Outreach to Water Managers

(Stakeholders: Legislators, Local Political Leaders & Community



DTSC/WB/CalEPA Mgmt, Needs

- Process improvement (streamlining)
 VCA Enforcement
- · Holistic Approach,
- Regulatory Integration Leverage resources (Modeling & GIS) Reduce Overlap
- & Consolidate Resources, Demonstration projects & Branding
- RCRA/CERCLA integration
- Align project Teams,
- . Develop DTSC Branding,
- · Establish Learning Organization,
- Establish Jurisdictional/coordination agreements (Output 1.1 4-2)
- Establish a portal for outsiders to access Teams Documents (Stakeholders: Director Perf Mgrs & Staff)

Outreach:

Industry Groups, RP Groups, Water Managers, Community Leaders, Political Leaders & Public

Water District/Business Needs

- · Process Streamlining Data Access, Cost Recovery Support (Lawsuit

- or sainy

 DTSCWD Legal agreement

 DTSC "discovery" support -VrD verify/identify

 Establish relationships with water managers (Output 1 1 1-1)
- Promote Transparency,
 Bring disparate groups together Participate in DWR Groundwater (Stakeholders: Water Managers)

Technical Requirements

- Cost Effective, Safe/Protective Remediation or Well Head Treatment Streamliner Process, Sound Science Basis
- New Conceptual Model
- · GIS development and distribution (Output 1 1.5)
- Integrate GAMA and USGS soils/geological data (Output & Outcome
- Streamline processes (Output 1 1.1-4 1 & 1 1.6-2)
- Integrate data bases & require e-deliverables integrate well logs & construction does & well abandonment does into EnviroStor,
- Develop well construction & abandonment standards (Output 1 1.1-5)
- . Evaluate point of compliance for new conceptual model (consider
- assimilative capacity)
 Integrate DPH Drinking Water Source Assessment (Output 1 1 1-2 Outcome 1.1.1-2) (Stakeholders: All)